

BRANCHES DEPARTMENT - PLANT REQUISITIONS

June 28, 1963

82 Bakersfield, Calif. #8486 - Repaint sales area, paint materials, install 9 new ballasts in lighting fixtures	\$292.20
195 Kenner, La. #7974 - Furnish & install 3-ton Coleman air conditioner/furnace	1,198.00
203 Borger, Tex. #7064 - Repairs to air conditioner	56.35
204 Utica, N. Y. #4187 - 1 Special porcelain 7' emblem	123.00
205 Seymour, Ind. #3762 - 1 Manager's chair	25.90
206 Atlanta, Ga. #2343 - Emergency repairs to truck	82.77
207 Beaver Dam, Wisc. #3003 - 1 Rolodex rotary file	21.72
208 Harriman, Tenn. #2642 - 2 Fluorescent fixtures w/lamps, installation	43.22
209 Milwaukee, Wisc. #3157 - 1 Cummins electric 1/2" drill	28.27
210 Atlanta, Ga. #2471 - Furnish & install 4 flood lights to illuminate fascia sign	75.00
211 Dallas, Tex. #7085 - 1 Friedrich 3-ton air conditioner/furnace unit, installation	1,127.00
212 Lawrenceville, Ga. #2041 - 8 Pair 36" stems & canopies, additional cost of installing air conditioner	120.00
213 Washington, D. C. #5870 - Repairs to elevator - overrun on P. R. #119	120.38
214 Atlanta, Ga. #2343 - 1 Derby sealer tape machine	13.00
215 Beaumont, Tex. #7733 - 1 Red Devil #30 Twin paint conditioner w/pedestal base	187.30
216 Laredo, Tex. #7461 - 1 Counter base for #30 paint conditioner	15.60
217 San Jose, Calif. #8517 - Furnish & install 550-gal. tank for mineral spirits, replace toilets and lavatories in two wash rooms	629.00
218 Norfolk, Va. #5072 - Replace burned out transformers in illuminated fascia sign, repair sign damaged by windstorm	127.50
219 Moberly, Mo. #6009 - Furnish & install 1 Chrysler Airtemp air conditioner	1,095.00
220 Quincy, Mass. #4801 - Repairs to sign	74.00
221 Austin, Tex. #7033 - Repairs to air conditioner	90.00
222 Decatur, Ill. #3105 - Furnish & install Westinghouse air conditioner	1,109.06
223 Belleville, N. J. #4113 - 1 Cabinet for Duro Art Supply vinyl letter & number assortment	15.06
224 Peoria, Ill. #3134 - 1 Red Devil #30 Twin paint conditioner w/pedestal base	187.30
225 Hopkinsville, Ky. #2020 - Repaint sales area; paint materials	224.48
226 Atlanta, Ga. #2444 - Repair truck damaged in accident	145.33
227 Jackson, Miss. #7308 - Repairs to GMC truck	75.78
228 Brownsville, Tex. #7404 - Repairs to truck	91.22
229 Salt Lake City, Utah #6451 - 1 Miller Model F paint conditioner w/timer & stand	163.80
230 Stapleton, N. Y. #4183 - 1 4-drawer file cabinet	36.91
231 Great Kills, N. Y. #4184 - 1 4-drawer file cabinet	36.91
232 Columbia, S. C. #2306 - Automotive mixing equipment	577.60
233 Bainbridge, Ga. #2913 - 1 Red Devil #30 Twin paint conditioner w/pedestal base, 1 MK-1 modernization kit for present conditioner	217.30
234 Columbia, S. C. #2306 - Repairs to hydraulic drum lift	50.89
235 Brick Town, N. J. #5097 - 8 Sections #4 steel shelving	111.84
236 Baltimore, Md. #5105 - 25 sections #1 steel shelving w/10 extra shelves	343.80
237 Camden, N. J. #5814 - Repairs to air conditioner	84.43
238 Leesburg, Fla. #2031 - 2 Displays for floor tile	107.64
239 Oklahoma City, Okla. #6661 - 1 Royal typewriter w/11" carriage and elite type	195.75
240 Riverdale, Md. #5010 - 1 National 9-HX adding machine	138.00
241 Mentor, Ohio #1105 - 5 sections #1 steel shelving; 24 18" x 36" steel shelves only	109.24
242 Wellington, Kans. #6032 - 1 Red Devil #30 Twin paint conditioner w/pedestal base	187.30
243 Sedalia, Mo. #6012 - Repairs to sign & interior electrical work	51.44
244 Homewood, Ill. #3083 - Paint 10' x 30' sign on side of building	153.00
245 Tulsa, Okla. #6333 - 1 National 9-EN electric adding machine	243.00
246 Greeneville, Tenn. #2684 - 1 National 9-EN electric adding machine	243.00
247 Essex, Md. #5968 - 1 Stationery cabinet	38.00
248 Woodbury, N. J. #5042 - Replace burned-out compressor in air conditioner, labor only	100.00

T O T A L . . .

\$10,583.29

0007-SWP-000026932A