



JUDGE FLORIDA HOSPITALITY BY THESE FINE HOTELS
 RADIO IN EVERY ROOM
 KLOEPEL HOTELS




HOTEL MAYFLOWER
JACKSONVILLE




NEW HOTEL JEFFERSON
JACKSONVILLE



HOTEL GEORGE WASHINGTON
JACKSONVILLE



WEST PALM BEACH



WEST PALM BEACH

Hotel George Washington

100% AIR CONDITIONED -- FINGER TIP CONTROL
 JACKSONVILLE 2, FLORIDA

Oct 18, 1949

Dr. Robert Kehoe.

Dear Bob:

I have shipped to you express a sample of sludge and sealer taken from a wing tank of one of Eastern Airline's planes. Would you please analyze for lead content and advise me of your findings. I am sure you will find it very low in lead content but it will help me in my work with Eastern Airlines.

I will give you a complete report of my work as soon as this problem is solved.

Yours truly.

R.L. Jordan
 R.L. Jordan

KE 0008118

N9621

EASTERN AIR LINES, INC.

RETURN ORDER

REPAIR AUTHORIZATION

N9 49553

P. O. Box 3581, Miami 30, Florida

INVOICE AND PACKING SHEET
MUST BEAR THIS NUMBERDate October 24 194 7

R L JORDEN
PO BOX 1791
DAYTONA BEACH, FLA.

~~STATION~~ EASTERN AIR LINES
Int'l Airport
Miami, Fla.

Shipped via AIRMAIL POST
Collect.....Prepaid.....

Via.....
F.O.B.....

Quantity	Part No.	Description of Part	() Cost of Repairs () Amount of Credit (Delete One)
1	177	Sample Gas tank dust	
1	181	Sample Tank Ceiling Comp.	
TIME ON PART:			

Instructions: The following items are returned to you under the following conditions:

Returned for chemical analysis. Please advise our Mr. E. T. Lee results of analysis.

- ☐ For Credit
- ☐ Overshipment
- ☐ Wrong Material
- ☐ Replacement
- ☐ Repair and Return
- ☐ Refill and Return
- ☐ Launder and Return
- ☐ Clean and Return
- ☐ Your inspection and recommendation
- ☐ Other

Remarks:

Our Reference:

Your Reference:

N9621.01

HIS/100