

Purpose: NPDES SSO Inspection Trip Report

Facility: Cahokia Heights, Illinois

NPDES ID Number (No NPDES Permit): ILN000019

Dates of Inspection: September 30, 2021

Illinois EPA Inspectors: None

EPA Inspectors:

Dean Maraldo, EPA Region 5; (312) 353-2098; maraldo.dean@epa.gov

Joan Rogers, EPA Region 5; (312) 886-2785; rogers.joan@epa.gov

Ted Flatebo, EPA Region 5; (312) 886-9402; flatebo.ted@epa.gov

City of Cahokia Heights Representatives: None

Inspection Trip Report Prepared by:

Joan Rogers, EPA Region 5 Inspector

EPA Inspector Signature: Maraldo, Dean Digitally signed by Maraldo, Dean
Date: 2021.10.21 13:40:19 -05'00'

EPA Inspector Signature: JOAN ROGERS Digitally signed by JOAN ROGERS
Date: 2021.10.21 08:06:54 -05'00'

EPA Inspector Signature: Flatebo, Theodore Digitally signed by Flatebo, Theodore
Date: 2021.10.21 14:09:59 -05'00'

Approver Name & Title:

Ryan Bahr, Chief, Compliance Section 2

Approval Signature and Date: RYAN BAHR Digitally signed by RYAN BAHR
Date: 2021.10.25 14:38:16 -05'00'

TABLE OF CONTENTS

I. Introduction..... 3
II. Inspection Activity Summary 3

Location #6: Lift Station #5

EPA inspectors arrived at Lift Station #5 at 10:54 A.M. This lift station is a former Centreville lift station and is located at 4200 Missouri Avenue. The lift station was not overflowing.