

Class I and II Well Inspection Form
US Environmental Protection Agency – Region 4
Underground Injection Control Program
61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303
Phone: (404)562-9424

Inspection ID

EPA Well ID#:	F	L	S	1	1	3	0	0	0	3
Year-Month-Day:	2	0	2	2	–	0	9	–	1	3
EPA Permit # (or RA):							8	1	5	
Page	1						Of		2	

Inspector(s): Jason Rose _____ (lead), Page Cirillo _____ Start Time: 8:20 AM _____
_____ End Time: 8:40 AM _____

Facility Contact Information

Facility Name: *Blackjack Plant* _____
Street Address: *4940 Blackjack Plant Road* _____
City: *Jay* _____ County: *Santa Rosa* _____ State: *FL* _____ Zip: *32535* _____
Nature of Business: *Oil and gas production* _____
Facility Owner/Operator: *Black Creek Energy, LLC* _____ Phone: *(601) 431-5386* _____
Email: *harris.butler@butlerroyals.com* _____
Facility Contact (if different): *Michael Wetzel* _____ Phone: *(850) 324-6271* _____
O/O Mailing Address: *140 Virginia Street, Suite 402* _____
City: *Richmond* _____ County: *NA* _____ State: *VA* _____ Zip: *23209* _____

Well Data from File

Well Name & #: *St. Regis Paper Co (SRPC) #15W* _____
Well Type (see table): *Enhanced Recovery (EOR)* _____ State Permit: API # *0911320147* _____
Latitude (°N): *30.858246°N* _____ Longitude (°W): *-87.135445°W* _____ Elevation (ft): *178'* _____
Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing

PBSD 16,146'

☐ Other: _____
Total Depth (ft): *16,250'* _____ Inner Casing Size (in): *7"* _____ Tubing Size (in): *3.5"* _____ Packer Depth (ft): *14,505'* _____
Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft): *15,818'* Bottom(ft): *15,891'* _____ Max. Injection Pressure (psig): *2,500 psi* _____

Field Measurements and Observations

Latitude (°N): *30.858188°N* _____ Longitude (°W): *-87.135390°W* _____ Elevation (ft): *NA* _____
EPA GPS ID: *PG No. 3358766066* _____ Well Status (see table): *AC* If not Active, Reported Date Last Active: _____
Nature of Injected Fluid(s) if any: _____
General Condition of the Well Site: The site is clean and well maintained. There was no evidence of leaks or excessive _____
Corrosion. _____
Notes & Comments (include discrepancies from database values): *At the time of inspection, the well was injecting at 1,680 psi. DEP indicated this well was formerly equipped with a nitrogen release to release pressure back to the plant, instead of bursting the well. DEP indicated that the connection has been disconnected and sealed off. The operator confirmed this statement. The EPA Inspection Team's visual inspection confirmed that it appears to be disconnected and sealed off. The site was clean and well-maintained. There was no evidence of leaks or excessive corrosion.*
Perfs (see well schematics):
Initial perfs (GRN & sonic): *16601- 16099' 2SPF July-76*
Added perfs (GRN & sonic): *16100-16144' 4 SPF Oct-83*

See reverse for additional observations, comments and photo log

Owner/Operator Representative (Optional)

Name: *Cliff Emmons* _____
Signature & Date: *see attached field notes* _____

UIC Inspector

Name: *Jason Rose* _____
Signature & Date: *Jason Rose* _____ *10/26/22* _____

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	0	3
	Year-Month-Day:	2	0	2	2	–	0	9	–	1	3
	EPA Permit # (or RA):							8	1	5	
					Page		2	Of		2	

[illegible]

Photographer: Jason Rose _____ EPA Camera ID: PG camera ID no. 14 S/N:31029537 _____

Photo ID: 1 _____ Time: 8:25 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking south, St. Regis Paper Company #15-W sign alongside access road.* _____

Photo ID: 2 _____ Time: 8:28 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking west, closeup view of surface pressure gauge reading 0 psi.* _____

Photo ID: 3 _____ Time: 8:28 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking west, closeup view of production casing pressure gauge reading 0 psi.* _____

Photo ID: 4 _____ Time: 8:29 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking west, closeup view of internal pressure gauge reading 1,680 psi.* _____

Photo ID: 5 _____ Time: 8:30 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking north, site overview including well head, pressure gauges, valves, and access stairs.* _____

Photo ID: 6 _____ Time: 8:31 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking east, view of pressure relief system formerly attached to well, which used to convey unused nitrogen back to the Black Creek gas plant. It is disconnected and sealed off.* _____

UIC Inspector

Name: Jason Rose _____

Signature & Date: Jason Rose 10/26/22

Site Photographs
St. Regis Paper Company #15-W
September 13, 2022



Photograph 1: Looking south, St. Regis Paper Company #15-W sign alongside access road.



Photograph 2: Looking west, closeup view of surface pressure gauge reading 0 psi.



Photograph 3: Looking west, closeup view of production casing pressure gauge reading 0 psi.



Photograph 4: Looking west, closeup view of internal pressure gauge reading 1,680 psi.



Photograph 5: Looking north, site overview including well head, pressure gauges, valves, and access stairs.



Photograph 6: Looking east, view of pressure relief system formerly attached to well, which used to convey unused nitrogen back to the Black Creek gas plant. It is disconnected and sealed off.