

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	3	4
						Year-Month-Day:	2	0	2	3	-	0	3	-	3	0
						EPA Permit # (or RA):	N	O	N	E						
						Page	1	Of	2							
Inspector(s): Carl E. Weller (lead), Carol Chen Start Time: 11:15 am																
End Time: 11:22 am																
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)															
	Street Address: 5415 Oil Plant Rd															
	City: Jay County: Santa Rosa State: FL Zip: 32565															
	Nature of Business: oil and gas production															
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702															
	Email:															
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319															
	O/O Mailing Address: 5415 Oil Plant Rd															
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565															
	Well Name & #: McDavid Lands #34-1 API No, 0911320111 PA No. 309897															
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_658															
	Latitude (°N): 30.99079281 Longitude (°W): -87.158975345 Elevation (ft):															
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing															
	PBTD: 15721' ☐ Other: surface casing															
	Total Depth (ft): 15830' Inner Casing Size (in): Tubing Size (in): Packer Depth (ft): 15275'															
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15444' Bottom(ft): 15498' Max. Injection Pressure (psig):															
Field Measurements and Observations	Latitude (°N): 30.99078 Longitude (°W): -87.15897 Elevation (ft):															
	EPA GPS ID: SX8123 Well Status (see table): SI If not Active, Reported Date Last Active:															
	Nature of Injected Fluid(s) if any:															
	General Condition of the Well Site:															
	Notes & Comments (include discrepancies from database values): A T-disk, showing the cross part, was installed on the nitrogen (N2) flowline, blocking gas injection. The produced water flowline is open for injection, without any T-disk, but there are no sounds of fluid flowing.															
	Perforations: Tubing gauge: 400 psi															
	15444' to 15498' (2SPF) 12/04/1980 Production gauge 0 psi															
	Surface gauge: 0 psi															
	This well passed a mechanical integrity test on 3/09/2023.															
	See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector								
Name: Carl E. Weller								Name: Carol Chen								
Signature: CARL WELLER (Affiliate)								Signature: CAROL CHEN								
Digitally signed by CARL WELLER (Affiliate) Date: 2023.05.23 15:12:20 -04'00'								Digitally signed by CAROL CHEN Date: 2023.05.22 14:00:11 -04'00'								
Version 2018-04-18																

Field Measurements and Observations (Cont.)

Inspection ID

F	L	S	1	1	3	0	0	3	4
---	---	---	---	---	---	---	---	---	---

2	0	2	3	-	0	3	-	3	0
---	---	---	---	---	---	---	---	----------	----------

N	O	N	E			
---	---	---	---	--	--	--

2

2

[illegible]

Photo Log

Photo ID: 200 Time: 11:13 am Lat (°N): 30.99078 Long (°W): -87.15897

Description: sign posted on the injection well itself, photo close-up

Photo ID: 201 Time: 11:14 am Lat (°N): 30.99084 Long (°W): -87.15897

Description: photo of the injection well, several feet away

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Name: CAROL CHEN Digitally signed by CAROL CHEN
Signature: Date: 2023.05.22 14:00:45 -04'00'