

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/02/2026	Time	09:40
		Operator Representative	McCann Resources, Inc		
Operator Info	McCann Resources, Inc 1613 West 6th Street Bartlesville, OK 740033404 Phone: 918-337-4747	Inventory ID	OS1679000		
		API Well No			
		Lease Name	W Bowring		
		Well ID	2-290		
Location	NE 28 28N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.879663	Longitude	-96.124117		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	McCann Resources, Inc		
Inspect No.		Date Last MIT	06/23/2015	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	160
Monitoring Device Elected	N	Tubings	Annulus	AUTHORIZED	
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 285
Lease Status	Active	Actual Pressure	Max Volume		
Barrel Monitor Hooked Up?	N	Determined?	Max Inj Units Barrels Per Month		
Barrel Fluid Level (%)		Static Fluid Level			
Flowline Hooked Up?	Y	Determined?			
Injecting	N	Injection Rate (bpd)			
Inspection Comments	At the time of the inspection, well OS1679000 was connected but not injecting. The flowline was hooked up but the tubing cutoff valve was closed preventing injection. The well tubing was reduced to 1" fittings which prevented observance of the fluid level with the EPA echometer which is equipped with standard 2" fittings. The well was overdue for MIT at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.879663, -96.124117		
City: Bowring	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010843

Orientation: NNW

Date of Photo: 04/02/2026

Time of Photo: 9:44AM

Latitude: 36.879663

Longitude: -96.124117

Photographer: Matthew Allen

Description: This was well OS1679000 at the time of the inspection. The well was overdue for MIT.