

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/03/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Basa Resources, Inc.	
Facility Name:	SS Laird A/C No. 1	
Facility Physical Location:	32.36763, -94.89362	
(city, state, zip code)	Kilgore, Texas 75662	
Mailing address:	14875 Landmark Blvd., Ste. 400	
(city, state, zip code)	Dallas, Texas 75254	
County/Parish:	Rusk County	
Facility Phone Number	214-580-5206	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011256	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Basa Resources, Inc. oil and gas facility located near Kilgore, Texas on 03/03/2020 for an unannounced inspection. There were no representatives of Basa Resources, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the SS Laird A/C No. 1. This facility has state identification number RRC No. 06972.

Section II - OBSERVATIONS

The secondary containment was inadequate at the time of the inspection. Drainage from creek and swampy area flow through and around the tank battery. Both the separating facility and main tank battery need secondary containment improvements.

Section III – AREAS OF CONCERN

There was inadequate secondary containment at the facility.

Section IV – FOLLOW UP

EPA water enforcement will refer this to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A