



REGION 4

ATLANTA, GA 30303

ELECTRONIC MAIL

CONFIRMATION OF RECEIPT EMAIL REQUESTED

Bryan Olier
General Manager
Jaxon Energy, LLC
455 Industrial Drive
Jackson, Mississippi 39209
bryanolier@jaxon-energy.com

Trey Richardson
Remediation Project Manager
Ashland Inc.
Atrium-North Tower Suite 500
5475 Rings Road
Dublin, Ohio 43017
trichardson@ashland.com

SUBJ: Resource Conservation and Recovery Act (RCRA) Compliance Evaluation Inspection (CEI)
Jaxon Energy, LLC / Ashland Inc.
EPA ID No.: MSR000106666 / MSD000829150

Dear Mr. Bryan Olier and Mr. Trey Richardson:

On February 13, 2024, the U.S. Environmental Protection Agency (EPA), along with the Mississippi Department of Environmental Quality (MDEQ) conducted a CEI at Jaxon Energy, LLC / Ashland Inc. located in Jackson, Mississippi to determine the facility's compliance status with RCRA and applicable regulations.

Enclosed is the EPA RCRA Inspection Report. If you have any questions regarding this matter, please contact Paula Whiting, by phone at (706) 355-8625 or by email at whiting.paula@epa.gov.

Sincerely,

ARACELI Digitally signed by
ARACELI CHAVEZ
Date: 2024.04.19
15:25:04 -04'00'
CHAVEZ

Araceli B. Chavez

Chief

RCRA Enforcement Section

Enclosure

1. RCRA Inspection Report

cc: Brad Justice, MDEQ, bjustice@mdeq.ms.gov
Nereida Hernandez Morales, EPA, hernandezmorales.nereida@epa.gov
Robert Nakamoto, EPA, nakamoto.robert@epa.gov