

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID		EPA Well ID#: F L S 1 1 3 0 0 7 5 Year-Month-Day: 2 0 2 4 – 0 5 – 0 1 EPA Permit # (or RA): F L I 0 0 4 5									
							Page 1 of 2									
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 9:40 am End Time: 9:45 am																
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating, LP)															
	Street Address: 5415 Oil Plant Rd															
	City: Jay County: Santa Rosa State: FL Zip: 32565															
	Nature of Business: oil and gas production															
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702															
	Email:															
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319															
	O/O Mailing Address: 5415 Oil Plant Rd City: Jay County: Santa Rosa State: FL Zip: 32565															
Well Data from File	Well Name & #: C. D. Helms Etal #5-4 API No. 09-113-20063 PA No. 309890															
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_558															
	Latitude (°N): 30.968922 Longitude (°W): -87.143947 Elevation (ft):															
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing															
	PBTD: 16019' ☐ Other: surface casing 9 5/8" at 3861' Smackover Formation															
	Total Depth (ft): 16110' Inner Casing Size (in): 7" at 16106' Tubing Size (in): 3 1/2" at 15570' Packer Depth (ft): 6100 psi															
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15708' Bottom(ft): 15821' Max. Injection Pressure (psig): 7500 N2 gas 4400psi PW															
Field Measurements and Observations	Latitude (°N): No GPS 000 Longitude (°W): No GPS 000 Elevation (ft):															
	EPA GPS ID: SC8284 Well Status (see table): TA If not Active, Reported Date Last Active: 3/20/22 Failed															
	Nature of Injected Fluid(s) if any: Mechanical Integrity Test (MIT)															
	General Condition of the Well Site:															
	Notes & Comments (include discrepancies from database values):															
See reverse for additional observations, comments and photo log																
UIC Inspector								UIC Inspector								
Name: Carol Chen								Name:								
Signature: CAROL CHEN								Signature:								

Digitally signed by CAROL CHEN
Date: 2024.06.20 21:53:41 -04'00'

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	7	5
	Year-Month-Day:	2	0	2	4	-	0	5	-	0	1
	EPA Permit # (or RA):	F	L	I	0	0	4	5			
					Page	2		Of	2		

[illegible]

Photographer: Carla Foy EPA Camera ID: SC8284

Photo ID: DSCN1371 Time: 9:42 am Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: well identification sign at the entrance

Photo ID: DSCN1372 Time: 9:44 am Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: injection well

Photo ID: DSCN1373 Time: 9:45 am Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: flow line pressure gauge reads 0 psi

Photo ID: DSCN1374 Time: 9:45 am Lat (°N): No GPS 000 Long (°W): No GPS 000

Description: injection tubing gauge reads 0 psi

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____