

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	3	0
Year-Month-Day:					2	0	2	4	-	1	0	-	2	2	
EPA Permit # (or RA):					R	A									
					Page	1		Of	2						
Inspector(s): Carol Chen (lead), Lonnie Dorn Start Time: 10:00 am															
End Time: 10:12 am															
Facility Contact Information	Facility Name: Slone Energy, LLC														
	Street Address: 8966 KY RT 40 West, P.O. Box 220														
	City: Oil Springs County: Magoffin State: KY Zip: 41238														
	Nature of Business: oil production														
	Facility Owner/Operator: Mr. S. Chris Slone, PE Phone: 606.297.5330 work														
	Email: chrisslone@sloneenergy.com														
	Facility Contact (if different): Phone: 606.225.2206 cell														
	O/O Mailing Address:														
Well Data from File	City: County: State: Zip:														
	Well Name & #: J. H. Arnett #W-8														
	Well Type (see table): Class II-R, Enhanced Oil Recovery (EOR) State Permit: 526-E8														
	Latitude (°N): 37.70721 Longitude (°W): -83.01234 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: 4 1/2" production casing														
	Total Depth (ft): Inner Casing Size (in): 2 3/8" Tubing Size (in): 1" Packer Depth (ft):														
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
	Latitude (°N): 37.707202 Longitude (°W): -83.012181 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): AC If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any: Produced Waters (PW)														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	The injection line is connected, feels icy cold. Produced waters are being injected to enhance oil recovery. No gauges were attached to monitor the injection and annulus pressures. The wellcap shows corrosion.														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.12.10 18:06:21 -05'00'								Version 2018-04-18							

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID EPA Well ID#: K Y S 1 5 3 0 1 3 0 Year-Month-Day: 2 0 2 4 - 1 0 - 2 2 EPA Permit # (or RA): R A Page 2 Of 2												
Field Measurements and Observations (Cont.)	(Cont) J. H. ARNETT #W-8 Class II-R, Enhanced Oil Recovery (EOR)															
	Photo Log	Photographer: Carol Chen EPA Camera ID: S75332														
Photo ID: RIMG0187 Time: 10:10 am Lat (°N): 37.707261 Long (°W) -83.012283																
Description: Injection well																
Photo ID: RIMG0188 Time: 10:10 am Lat (°N): 37.707202 Long (°W) -83.012181																
Description: Close-up view of injection well																
Photo ID: Time: Lat (°N): Long (°W)																
Description:																
Photo ID: Time: Lat (°N): Long (°W)																
Description:																
Photo ID: Time: Lat (°N): Long (°W)																
Description:																
UIC Inspector								UIC Inspector								
Name: Carol Chen								Name:								
Signature: CAROL CHEN								Signature:								
Digitally signed by CAROL CHEN Date: 2024.12.10 18:06:49 -05'00'								Version 2018-04-18								