

## Region 6 - Enforcement & Compliance Assurance Division

### INSPECTION REPORT

|                                        |                                                              |                               |
|----------------------------------------|--------------------------------------------------------------|-------------------------------|
| Inspection Date(s):                    | 12/11/2023                                                   |                               |
| Media Program:                         | Water                                                        |                               |
| Regulatory Program(s)                  | Clean Water Act                                              |                               |
| Company Name:                          | <b>Jamie Oil, Inc.</b>                                       |                               |
| Facility Name:                         | <b>Brown 4x Tank Battery</b>                                 |                               |
| Facility Physical Location:            | Latitude: 33.23419, Longitude: -92.5956                      |                               |
| (city, state, zip code)                | El Dorado, AR, 71730                                         |                               |
| Mailing address:                       | 1190 Cedarglade Road                                         |                               |
| (city, state, zip code)                | Hot Springs, Arkansas, 71913                                 |                               |
| County/Parish:                         | Union County                                                 |                               |
| Facility Phone Number                  | 870-814-5299                                                 |                               |
| Facility Contact:                      | Jimmy Crain                                                  |                               |
|                                        | <a href="mailto:jcrain454@yahoo.com">jcrain454@yahoo.com</a> |                               |
| FRS Number:                            | NA                                                           |                               |
| Identification/Permit Number:          | ARU002201                                                    |                               |
| Media Identifier Number:               | NA                                                           |                               |
| NAICS:                                 | 211111                                                       |                               |
| SIC:                                   | 1311                                                         |                               |
| Personnel participating in inspection: |                                                              |                               |
| Chelsey Sherwood                       | EPA/Region 6 ECDW                                            | Enforcement Officer/Inspector |
| Michael Blaha                          | EPA/Region 6 ECDW                                            | Enforcement Officer/Inspector |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
|                                        |                                                              |                               |
| EPA Lead Inspector<br>Signature/Date   |                                                              | 1/30/2024                     |
|                                        | Chelsey Sherwood                                             | Date                          |
| Supervisor<br>Signature/Date           |                                                              |                               |
|                                        | Jeanne Eckhart (acting Chief Mitty Garcia)                   | Date                          |

## **Section I – INTRODUCTION**

### **PURPOSE OF THE INSPECTION**

EPA Region 6 inspectors Chelsey Sherwood and Michael Blaha arrived at Jamie Oil, Inc., Brown 4x Tank Battery, located off O D Road (33.23419, -92.5956) at 4:10 PM on 12/11/2023 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

### **FACILITY DESCRIPTION**

EPA conducted an inspection on Jamie Oil, Inc., Brown 4x Tank Battery which contains two oil tanks and a heater treater that is out of service.

## **Section II - OBSERVATIONS**

I observed the facility sign, secondary containment, oil tanks, heater treater, and pipes located at the facility, see Appendix 1 (photo log), photo No. 1 for additional GPS location and photo metadata, see Appendix 1.

## **Section III – AREAS OF CONCERN**

No closing conference was held due to no Jamie Oil, Inc. staff being present during the inspection. There were no areas of concern at the time of the inspection.

## **Section IV – FOLLOW UP**

Inspector will email report to company, but no areas of concern were noted at the time of inspection and therefore no follow up is needed.

## **Section V – LIST OF APPENDICES**

Appendix 1 – Photo Log – 2 photos taken 12/11/2023

## Appendix 1

### Photograph Log

2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## Photograph Log

Photo No. 1

|                              |                      |                 |
|------------------------------|----------------------|-----------------|
| Location: 33.23419, -92.5956 |                      |                 |
| City: El Dorado              | County/Parish: Union | State: Arkansas |



**Photo File Name:** 6186

**Orientation:** N

**Date of Photo:** 12/11/2023

**Time of Photo:** 4:20 PM

**Latitude:** 33.23419

**Longitude:** -92.5956

**Photographer:** Chelsey Sherwood

**Description:** This photo was taken looking NW at the facility showing the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## Photograph Log

Photo No. 2

|                              |                      |                 |
|------------------------------|----------------------|-----------------|
| Location: 33.23419, -92.5956 |                      |                 |
| City: El Dorado              | County/Parish: Union | State: Arkansas |



**Photo File Name:** 6187

**Orientation:** N

**Date of Photo:** 12/11/2023

**Time of Photo:** 4:20 PM

**Latitude:** 33.234262

**Longitude:** -92.595499

**Photographer:** Chelsey Sherwood

**Description:** This photo was taken looking N at the facility showing an overview of the facility.