

Inspection Report Addendum for Well: MT20766-04256
Inspection Date: 10/25/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04256 (102-W17R), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 1 of 6	Time: 9:38 am		
Photo Description: Well sign by wellhead.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04256 (102-W17R), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 2 of 6	Time: 9:38 am		
Photo Description: Wellhead is observed to be disconnected from flowline (right of the wellhead). Operator notes well configuration to be: 2 3/8" tubing within 4 1/2" casing within 7" casing. Operator noted that 4 1/2" casing is cemented to 7" casing			

Inspection Report Addendum for Well: MT20766-04256
Inspection Date: 10/25/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04256 (102-W17R), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 3 of 6	Time: 9:38 am		
Photo Description: Closer view of wellhead configuration 2 3/8" tubing within 4 1/2" casing within 7" casing. Operator noted that 4 1/2" casing is cemented to 7" casing			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04256 (102-W17R), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 4 of 6	Time: 9:39 am		
Photo Description: Closer view of wellhead tubing. Master ball valve for tubing was in closed position.			

Inspection Report Addendum for Well: MT20766-04256
Inspection Date: 10/25/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04256 (102-W17R), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 5 of 6	Time: 9:43 am		
Photo Description: EPA's digital pressure gauge on the tubing read 627 psi on a 3000-psi range gauge. MAIP for well is 2638 psi.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04256 (102-W17R), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/25/2023			
Photo No. 6 of 6	Time: 9:39 am		
Photo Description: Tubing-casing annulus observed to be maintained continuously open to atmospheric pressure.			

Inspector signature

Inspector signature

Inspector signature