

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	12/10/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Senax, Inc.	
Facility Name:	Stuart Whitetail	
Facility Physical Location:	36.787977, -96.25583 (SW Sect. 29, T 27N, R 10E)	
(city, state, zip code)	Pawhuska, Oklahoma 74056	
Mailing address:	1844 E. 31st Place	
(city, state, zip code)	Tulsa, Oklahoma 74105	
County/Parish:	Osage County	
Facility Phone Number	918-494-0681	
Facility Contact:	Daphne Wise	
	daphne@senaxinc.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		18 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Senax, Inc. oil and gas facility located at latitude 36.787977 and longitude -96.25583 near Pawhuska, Oklahoma on 12/10/2019 for an unannounced inspection. There were no representatives of Senax, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the Stuart-Whitetail lease.

Section II - OBSERVATIONS

I observed that the secondary containment area was dry and had adequate berms. There was surface damage west and south of the tank battery outside of containment.

Section III – AREAS OF CONCERN

N/A

Section IV – FOLLOW UP

N/A

Section V – LIST OF APPENDICES

N/A