

LEAK DETECTION REPORTING FORM

ABERDEEN PVC PLANT

1. Honeywell Chromatograph No.	#1
2. Date	12/27
3. Time	2400
4. Monitoring Point With High Readings	3 3 3 3 3
5. Readings, PRM	10 10 10 1.6 .3 0
6. Operator Action Result	Checked out Area with Det with Dumping Blue Down tank
7. Shift Supervisor Action Result	
8. Maintenance Action Result	1st reading of the dump tank level
9. Verified By	check this J. Brant
10. Operator	Shift Supervisor R. Reed

DTH 000105083