

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 05/06/2025		Time 08:15	
Operator Representative 2020 Harris Partners, LLC		Report Sent Operator			
Inject Interval 1867 - 2500		USDW 180		Well Type Disposal	
Annulus Fluid Type Water		Concentric Pkr		Packer Depth 1756	
Casing 4.5		Tubing 2.375			
Operator Info 2020 Harris Partners, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS4482000		
			API Well No		
			Lease Name Ochelata Jumas		
			Well ID JD-1		
			Location NW 22 25N 12E		
Type of MIT Casing - Tubing Annulus Pressure			Test Reason Routine		
Injecting Y		Injection Rate (bpd)		Tubular Lining	
MIT Due 01/04/2023		MIT Freq EVERY FIVE YEARS		Ann Filled (hrs)	
				Ann Press Mont	
Time		Tubing Pressure		Annulus Pressure	
Flowback		Pressure		Volume	
Pre-Test		-25		210	
Initial 08:15		-25		210	
Mid 08:30		-25		210	
Final 08:45		-25		210	
		High		210	
		Mid		100 1500	
		Low		20 1400	
		End		0 100	
		Total Volume		3000	
			ADA Pressure Test - Required Test Pressure		
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)		
			Tubing		
			Annulus		
			Depth to Top Perf/Open Hole		
			Depth to Fluid Level		
			Fluid Column Level		
			Specific Gravity of Fluid		
			Nitrogen Weight Factor		
Required Pressure Test					
Remedial Action Type					
Fluid Migration Test Type		Remedial Action Type			
Inspection Comments		Inspector observed the MIT for well OS4482000. Well was pressured to the required test pressure and maintained the pressure throughout the required observance period.			
Inspector Signature		MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2025.05.28 15:23:01 -05'00'			
Supervisor Signature		JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2025.06.03 06:01:44 -05'00'			

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.632652, -96.007288		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010664

Orientation: WSW

Date of Photo: 5/6/2025

Time of Photo: 8:30 AM

Latitude: 36.632652

Longitude: -96.007288

Photographer: Matthew Allen

Description: This was well OS4482000 at the time of the inspection.