

Westover Salvage Inc.


March 17, 2023

Damian Bednarz – Inspector

Jeremy Rolfe – ECAD

























































































Building floor is
sloped toward drain.

03/17/2023












































03/17/2023











03/17/2023



This catchment area is
at the back of the
property; water flows
from the car yard to this
point.

03/17/2023






























































































Top of Tire Pile

Toward Brook/Wetland





















