

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	4	7
Year-Month-Day:					2	0	2	4	-	0	4	-	3	0	
EPA Permit # (or RA):					F	L	I	0	0	3	1				
					Page		1		Of		2				
Inspector(s): _____ (lead), _____ Start Time: 4:45 pm															
_____ End Time: 4:49 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email: _____														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
City: Jay County: Santa Rosa State: FL Zip: 32565															
Well Data from File	Well Name & #: Lawrence L. Malone Et Ux #41-4A API No. 09-113-20167-01														
	Well Type (see table): Producer (EOR if converted to injection) State Permit: OG_944A PA#309901														
	Latitude (°N): 30.95675654 Longitude (°W): -87.15610762 Elevation (ft): _____														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: intermediary casing 7½" @15746' surface casing 16" @3780'														
	Total Depth (ft): 15712' Inner Casing Size (in): 5½" 14994' Tubing Size (in): 3½" 14976' Packer Depth (ft): _____														
Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) 15689' Bottom(ft): 15741' Max. Injection Pressure (psig): _____															
Field Measurements and Observations	Latitude (°N): No GPS 000 Longitude (°W): No GPS 000 Elevation (ft): _____														
	EPA GPS ID: SC8284 Well Status (see table): AC If not Active, Reported Date Last Active: _____														
	Nature of Injected Fluid(s) if any: Nitrogen (N2) Gas Injection														
	General Condition of the Well Site: _____														
	Notes & Comments (include discrepancies from database values): _____														
	This well is actively injecting Nitrogen (N2) Gas.														
	Tubing gauge: 200 psi														
	Production gauge: 0 psi														
	Surface gauge: 0 psi														
	Flow line gauge: _____														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name: _____							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.06.20 21:35:59 -04'00'								Signature: _____							
Version 2018-04-18															

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	4	7
	Year-Month-Day:	2	0	2	4	–	0	4	–	3	0
	EPA Permit # (or RA):	F	L	I	0	0	3	1			
						Page	2	Of	2		

Photo Log

Photographer: Carol Chen

EPA Camera ID: SC8284

Photo ID: DSCN1356

Time: 4:47 pm

Lat (°N): No GPS 000

Long (°W): No GPS 000

Description: production gauge reads 0 psi

Photo ID: DSCN1357

Time: 4:47 pm

Lat (°N): No GPS 000

Long (°W): No GPS 000

Description: surface gauge reads 0 psi

Photo ID: DSCN1358

Time: 4:49 pm

Lat (°N): No GPS 000

Long (°W): No GPS 000

Description: tubing gauge reads 200 psi

Photo ID:

Time:

Lat (°N):

Long (°W):

Description:

Photo ID:

Time:

Lat (°N):

Long (°W):

Description:

Photo ID:

Time:

Lat (°N):

Long (°W):

Description:

UIC Inspector Name: <u>Carol Chen</u> Signature: <u>CAROL CHEN</u> Digitally signed by CAROL CHEN Date: 2024.06.20 21:36:26 -04'00'	UIC Inspector Name: _____ Signature: _____ Version 2018-04-18
---	--