

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/04/2022	Time	11:00
Inspection Due	2024-01-04T00:00:00Z	Operator Representative	Raptor Resources, LLC		
Operator Info	Raptor Resources, LLC 63555 North Indigo Trail Owasso, OK 74055 Phone: 918-440-3585	Inventory ID	OS6498000		
		API Well No			
		Lease Name	McComb		
		Well ID	16		
Location	SW 01 27N 07E	Status	Active	Well Type	Disposal
Latitude	36.84299	Longitude	-96.505043		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Raptor Resources, LLC		
Inspect No.		Date Last MIT	01/04/2022	Last Test Result	Acceptable
Casing		Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure
FLM Canister Pressure		Actual Pressure	-30	0	Max Volume
Lease Status	Active	Determined?	Compan y Gage	Compan y	Max Inj Units
Barrel Monitor Hooked Up?	Y	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)	1528		
Injecting	Y				
Inspection Comments	At the time of the inspection, well OS6498000 was connected and injecting at a rate of 1528 barrels per day (BPD) and the barrel monitor displayed a cumulative total of 1539 barrels. The pressure gauge on the tubing displayed 30 in.Hg vacuum. The pressure gauge on the annulus displayed 0 psi. The continuous pressure monitoring chart recorder was properly attached to the tubing of the well. The operator should install an accurate, legible well sign displaying the EPA inventory ID number. There were no areas of concern at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 3 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.842945, -96.505025		
City: Foraker	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0657

Orientation: N

Date of Photo: 08/4/2022

Time of Photo: 11:02 AM

Latitude: 36.842945

Longitude: -96.505025

Photographer: Matthew Allen

Description: This was the McComb No. 16 (OS6498000) well. At the time of the inspection the continuous pressure monitoring chart device was properly connected and functioning.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.842945, -96.505025		
City: Foraker	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0658

Orientation: NW

Date of Photo: 08/4/2022

Time of Photo: 11:02 AM

Latitude: 36.842945

Longitude: -96.505025

Photographer: Matthew Allen

Description: This was a view of the proper installation of the pressure monitoring device onto the tubing of the well.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 36.842945, -96.505025		
City: Foraker	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0659

Orientation: n/a

Date of Photo: 08/4/2022

Time of Photo: 11:02 AM

Latitude: 36.842945

Longitude: -96.505025

Photographer: Matthew Allen

Description: This was the well sign inside the fence at the well location. Updated, legible signage should be maintained at the well location.