



REGION 4

ATLANTA, GA 30303

SENT VIA ELECTRONIC MAIL

Jerry McKneely
Owner
Haggai Truck Center, LLC
1228 High Falls Road
Griffin, Georgia 30223
hdieselrepair@gmail.com

Dear Jerry McKneely:

Enclosed is a copy of the final inspection report generated by the U.S. Environmental Protection Agency's Region 4 Air Enforcement Branch for the on-site compliance inspection conducted at the Haggai Truck Center, LLC (Haggai Truck Center) facility located in Griffin, Georgia on July 30, 2024.

The EPA previously sent Haggai Truck Center a copy of the draft inspection report via File Transfer Protocol on September 17, 2024, allowing Haggai Truck Center the opportunity to make comments on the report and to claim any information contained in the report as confidential business information (CBI). The EPA requested that Haggai Truck Center review the report and respond no later than September 25, 2024. As of October 2, 2024, Haggai Truck Center has not provided any comments or made a CBI claim.

Should you have any questions regarding this inspection report, please contact me at (404) 562-8971 or spann.tony@epa.gov.

Sincerely,

TONY
SPANN

Digitally signed by TONY
SPANN
Date: 2024.10.03
10:25:52 -04'00'

Tony Spann
Life Scientist
North Air Enforcement Section

Enclosures

INSPECTION REPORT
Facility Name: Haggai Truck Center, LLC

Attached please find the United States Environmental Protection Agency's (EPA's) inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to a Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Number:	3601698175-2024
Inspection Date(s):	July 30, 2024
Regulatory Program(s):	Clean Air Act Title II: Mobile Source
EPA Region/Program Conducting Inspection:	U.S. EPA, Region 4 Air Enforcement Branch
Company Name:	Haggai Truck Center, LLC
Facility Name:	Haggai Truck Center, LLC
Facility Street Address:	1228 High Falls Road
Facility City, State, Zip Code:	Griffin, Georgia 30223

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Supervisor Approval

Tony Spann
Field Inspector Name

**TONY
SPANN**

Digitally signed by TONY
SPANN
Date: 2024.10.03
10:26:46 -04'00'

Field Inspector Signature

10/3/24
Date

Jason Dressler
Name of Approving Official

Chief, NAES
Title

**JASON
DRESSLER**

Digitally signed by JASON
DRESSLER
Date: 2024.10.02
14:41:56 -04'00'

Approving Official Signature

10/2/24
Date

INSPECTION REPORT

Facility Name: Haggai Truck Center, LLC

General Inspection Information			
Inspector(s):	Tony Spann, Carrie Griffith	Arrival Date/Time:	07/30/2024 / 10:52 a.m. EDT
Primary Facility Representative & Title:	Jerry McKneely, Owner	Departure Date/Time:	07/30/2024 / 12:24 a.m. EDT
Facility Contact Phone/Email:	678-544-1614 / hdieselrepair@gmail.com	Compliance Assistance Reference Materials Provided to Facility:	☒ SBREFA Form ☒ Enforcement Alert ☐ EPA Tampering Policy ☐ Copy of CAA § 203(a)(3) ☐ Copy of CAA § 114 ☐ §208/§114 Preservation Letter ☒ Discussion of Right to Claim CBI ☐ Other:
Time Inspector(s) Presented Credentials:	10:52 a.m. EDT		
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	Yes / Katelyn McKneely		
Photograph Range:	0635 – 0641	Photographer Name:	Carrie Griffith
Notes:	Haggai Truck Center is an auto repair shop in Griffin, GA, specializing in servicing diesel vehicles.		

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☐	Sells aftermarket parts		
☒	Service Shop	Haggai Truck Center provides repair and maintenance services for diesel vehicles specifically tractor trailers. A majority of the service includes engine and camshaft overhauls and major repairs.	2 to 3 vehicle repairs/week
☐	Fleet		
☐	Other		
Notes			

INSPECTION REPORT

Facility Name: Haggai Truck Center, LLC

Personnel Interviewed			
Name	Title	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Katelyn McKneely	Company Representative	678-688-8107 / hdieselrepair@gmail.com	Spann, Griffith

Documents Requested		
Document Requested	Status	Notes/Comments
Service invoices for May 2024 through July 2024	☐ Document Provided ☐ Document Request Denied ☒ Facility Agreed to Provide After Inspection ☐ Other (add notes)	Requested service invoices have not been received as of October 1, 2024. Facility personnel indicated on September 27, 2024, that invoices will be provided electronically.
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	

Vehicles Inspected/Observed				
VIN (last 8 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Scan Conducted? (Yes/No)	Observations
FJ472637	Not observed	No	Yes	Inspectors observed exterior of vehicle and utilized data logger to scan and capture vehicle's data. Inspectors did not observe emission control devices on vehicle's exhaust aftertreatment.

PHOTOGRAPH LOG

Haggai Truck Center, LLC

Image Number	File Name	Date	Time (EDT)	Description of Image
1	IMG_0635	7/30/2024	11:49	Vehicle 1 – left front
2	IMG_0636	7/30/2024	11:49	Vehicle 1 – right side
3	IMG_0637	7/30/2024	11:49	Vehicle 1 – rear
4	IMG_0638	7/30/2024	11:49	Vehicle 1 – rear
5	IMG_0639	7/30/2024	11:49	Vehicle 1 – label
6	IMG_0640	7/30/2024	11:50	Vehicle 1 – label
7	IMG_0641	7/30/2024	11:50	Vehicle 1 – label

Photographs were taken by EPA inspector Carrie Griffith.