

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	12/21/2022	Time	12:00
Inspection Due	2021-04-03T00:00:00Z	Operator Representative	Grace Energy Management, Inc.		
Operator Info	Grace Energy Management, Inc. P.O. Box 515 Cement, OK 73017 Phone: 405-489-7126	Inventory ID	OK0089000		
		API Well No			
		Lease Name	SECEPSU (Kla-Da-Ing 7)		
		Well ID	7-1		
Location	NW 10 05N 09W	Status	Active	Well Type	Enhanced Recovery
Latitude	34.924667	Longitude	-98.142667		
Inspection Reason	MIT	Responsible Company at Time of Inspection	Grace Energy Management		
Inspect No.		Date Last MIT	07/28/2016	Last Test Result	Acceptable
Casing	5.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 905
FLM Canister Pressure		Actual Pressure	700		Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OK0089000. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Initial: 240psi Mid: 245psi Final: 250psi Pressure Hold OK Total flowback: 7,000ml				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 34.924667, -98.142667		
City: Verden	County/Parish: Grady	State: Oklahoma



Photo File Name: R0010014

Orientation: SE

Date of Photo: 12/21/2022

Time of Photo: 12:00 PM

Latitude: 34.924667

Longitude: -98.142667

Photographer: Matthew Allen

Description: OK0089000 well sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 34.924667, -98.142667		
City: Verden	County/Parish: Grady	State: Oklahoma



Photo File Name: R0010015

Orientation: SE

Date of Photo: 12/21/2022

Time of Photo: 12:00 PM

Latitude: 34.924667

Longitude: -98.142667

Photographer: Matthew Allen

Description: Well, OK0089000 with EPA gauge and bleeder attached, just before pressuring for MIT.