

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Jeanne Eckhart	Inspection Date	02/15/2022	Time	10:00
Inspection Due		Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS3494000		
		API Well No			
		Lease Name	Tidal Osage		
		Well ID	2-6		
Location	SE 24 24N 08E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.536793	Longitude	-96.395526		
Inspection Reason	Emergency Response Complaint Response	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT		Last Test Result	
Casing	4.5	Tubing		USDW	
Monitoring Device Elected		Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 586
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	TA'd well. Complainant indicated well has been in this condition for many years. Tubing was open to atmosphere during inspection, and casing closed by valves. Cement lined tubing rotted off at slips. See Inspection Photo Log attachment (1 photo).				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.5369664, -96.3956121		
City: Wynona	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0502.JPG

Orientation: South

Date of Photo: 2/15/2022

Time of Photo: 10:09 am

Latitude: 36.5369664N

Longitude: -96.3956121W

Photographer: Carl Wills

Description: This was an overview image of the temporarily abandoned injection well on the Tidal I Osage Lease. The tubing was open to the atmosphere and the casing appeared to be closed by valves. The injection well was disconnected.