

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	8	0
Year-Month-Day:					2	0	2	4	–	0	4	–	3	0	
EPA Permit # (or RA):					F	L	I	0	0	5	2				
					Page		1		Of		2				
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 1:18 pm															
End Time: 1:38 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Well Name & #: McMillan #7-10 API No. 09-113-20271														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_1363														
	Latitude (°N): 30.98029639 Longitude (°W): -87.17839333 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 15589' ☐ Other: surface casing 10 3/4" at 3783														
	Smackover Formation														
	Total Depth (ft): 15689' Inner Casing Size (in): 4 1/2" at 15689' Tubing Size (in): 3 1/2" at 14111' Packer Depth (ft): 14111'														
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15328' Bottom(ft): 15526' Max. Injection Pressure (psig): 7120 psi														
	Latitude (°N): 30.980368 Longitude (°W): -87.178312 Elevation (ft):														
	EPA GPS ID: Well Status (see table): AC If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any: Produced Waters (PW)														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	DANGER sign: H2S May Be Present...Authorized Personnel Only...Caution..Hazardous Operations...														
	The Produced Waters (PW) Manifold has two gauges. In addition, Tubing gauge: 2400 psi														
a flowline gauge at the injection well reads 2300 psi. Production gauge: 0 psi															
Surface gauge: 150 psi															
Low ladder at injection well with light-yellow fluorescent paint. Flow line gauge 2300 psi															
H2O Manifold with two gauge readings: 2700 psi, 2350 psi															
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.06.20 21:42:41 -04'00'															
Version 2018-04-18															

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 8 0									
Year-Month-Day: 2 0 2 4 – 0 4 – 3 0															
EPA Permit # (or RA): F L I 0 0 5 2															
Page 2 Of 2															

Field Measurements and Observations (Cont.)

(Cont)

McMillan #7-10

State Permit No. OG_1363

API No. 09-113-20271

Perforations (Smackover Formation):

15328' to 15336' on 5/26/2017

15361' to 15391' on 5/26/2017

15432' to 15448' on 5/26/2017

15516' to 15526' on 5/26/2017

Photo ID: RIMG0125

Time: 1:30 pm

Lat (°N): 30.980325

Long (°W) -87.17836

view of injection well with fluorescent-yellow painted lower staircase and DANGER sign: H2S...

Photo ID: RIMG0126

Time: 1:31 pm

Lat (°N): 30.98935

Long (°W) -87.178323

back of the injection well with piping and H2O flowline

Photo ID: RIMG0127

Time: 1:32 pm

Lat (°N): 30.980443

Long (°W) -87.17829

surface gauge reads 150 psi

Photo ID: RIMG0128

Time: 1:32pm

Lat (°N): 30.98042

Long (°W) -87.178317

annulus gauge reads 0 psi

Photo ID: RIMG0129

Time: 1:35pm

Lat (°N): 30.980368

Long (°W) -87.178312

close-up of tubing gauge, reads 2400 psi

Photo ID: RIMG0130

Time: 1:36 pm

Lat (°N): 30.98037

Long (°W) -87.178285

flowline gauge at 2300 psi

Photo Log

Photographer: Carol Chen

EPA Camera ID: S75332

Photo ID: RIMG0119

Time: 1:20 pm

Lat (°N): No GPS 000

Long (°W) No GPS 000

Description: sign posted some distance from the injection well, showing well's identification

Photo ID: RIMG0120

Time: 1:24 pm

Lat (°N): 30.958097

Long (°W) -87.188063

Description: 1st gauge viewed on the H2O manifold at 2700 psi

Photo ID: RIMG0121

Time: 1:25 pm

Lat (°N): 30.963478

Long (°W) -87.185638

Description: farther back view of the 1st gauge on the H2O manifold at 2700 psi

Photo ID: RIMG0122

Time: 1:25 pm

Lat (°N): 30.97698

Long (°W) -87.179343

Description: different angle, 1st gauge on the H2O manifold at 2700 psi

Photo ID: RIMG0123

Time: 1:27 pm

Lat (°N): 30.977561

Long (°W) -87.179343

Description: 2nd gauge viewed on the H2O manifold at 2350 psi

Photo ID: RIMG0124

Time: 1:28 pm

Lat (°N): 30.979247

Long (°W) -87.178238

Description: farther back, overall view of the H2O manifold with 2 gauges

UIC Inspector		UIC Inspector	
Name: Carol Chen		Name:	
Signature: CAROL CHEN		Signature:	
Digitally signed by CAROL CHEN Date: 2024.06.20 21:43:08 -04'00'			

Version 2018-04-18