

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	01/16/2025	
Media Program:	Water (CWA)	
Regulatory Program(s)	Water (CWA) Brine Program (Oil & Gas inspection)	
Company Name:	Rheba SWD, LLC (dba Capstone Oilfield Disposal of Arkansas, LLC)	
Facility Name:	Rheba 20-2 SWDS Tank Battery	
Facility Physical Location:	In between Center Valley and Moreland (Russellville) from Interstate 40, then right on Highway 124, then right onto Highway 326, and right onto a gas lease road at 35.328333, -93.043333.	
(city, state, zip code)	Russellville, AR, 72802	
Mailing address:	400 W Jack H. Choate Ave	
(city, state, zip code)	Hennessey, OK 73742	
County/Parish:	Pope County	
Facility Phone Number	405-853-7170	
Facility Contact:	Chase Holder (405-853-1540)	Person Responsible for Operation
	cholder4@icloud.com	
FRS Number:	N/A	
Identification/Permit Number:	ARU002278; ADEQ State No-Discharge Permit 0825-WG-SW-3 (AFIN 58-00780)	
Media Identifier Number:	N/A	
NAICS:	213112	
SIC:	1389	
Personnel participating in inspection:		
Kerri McCabe (lead)	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Kerri McCabe	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 Inspector Kerri McCabe (lead) arrived at the Rheba SWD, LLC / Rheba 20-2 SWDS Tank Battery (“facility”) at 1100 on 01/16/2025 for an announced inspection. The facility is located outside Russellville, Pope County, Arkansas from Interstate 40, then right on Highway 124, then right onto Highway 326, and right onto a gas lease road at 35.328333, -93.043333. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

EPA conducted an inspection on the Rheba SWD, LLC / Rheba 20-2 SWDS Tank Battery, which contained one (1) tank battery, three (3) storage frac tanks for produced water, one (1) unloading containment area, and one (1) Class II saltwater disposal (SWD) injection well.



Map 1. Aerial imagery (Google Earth dated 01/04/2023) of the Rheba SWD, LLC / Rheba 20-2 SWDS Tank Battery.

Section II – OBSERVATIONS

I observed the Rheba SWD, LLC / Rheba 20-2 SWDS Tank Battery signage, see Appendix 1 (Photograph Log), Photo No. 1. For additional GPS location and photo metadata, see Appendix 1.

Section III – AREAS OF CONCERN

No closing conference was held due to no personnel with Rheba SWD, LLC being present during the inspection.

Section IV – FOLLOW UP

I was unable to access the facility at the time of the inspection due to a locked gate. A joint inspection with EPA and AOGC is scheduled for 02/13/2025.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 1 photo taken 01/16/2025.

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: From Interstate 40, then right on Highway 124, then right onto Highway 326, and right onto a gas lease road at 35.328333, -93.043333

City: Russellville

County/Parish: Pope

State: Arkansas



Photo File Name: 100-0467

Orientation: 326° NW

Date of Photo: 01/16/2025

Time of Photo: 1111

Latitude: 35.336967

Longitude: -93.043450

Photographer: Kerri McCabe

Description: Looking NW, this photo shows the signage for the facility at a locked gate.