

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/24/2022	Time	15:30
Inspection Due	2021-03-31T00:00:00Z	Operator Representative	NuCera Solutions LLC		
Operator Info	NuCera Solutions LLC P.O. Box 669 Barnsdall, OK 74002 Phone: 9188473272	Inventory ID	OK9006000		
		API Well No			
		Lease Name	NA		
		Well ID	1		
Location	SE 18 24N 11E	Status	Active	Well Type	Non-Hazardous Industrial
Latitude	36.5536	Longitude	-96.158867		
Inspection Reason	MIT	Responsible Company at Time of Inspection	NuCera Solutions LLC		
Inspect No.		Date Last MIT	04/01/2019	Last Test Result	Acceptable
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 500
FLM Canister Pressure		Actual Pressure	40	265	Max Volume 123420
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	MIT Conducted - Standard Annulus Pressure Test (SAPT) (30 Minutes) Start pressure: 265 Mid Pressure: 263 End Pressure: 263 Pressure hold OK Total flowback = 5,800 ml No well records provided at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.5536, -96.158867		
City: Barnsdall	County/Parish: Osage	State: Oklahoma




Photo File Name: DSCN0830

Orientation: SW

Date of Photo: 10/24/2022

Time of Photo: 4:13 PM

Latitude: 36.5536

Longitude: -96.158867

Photographer: Matthew Allen

Description: This was the well OK9006000. EPA inspector observed NuCera Solutions LLC, and contract personnel perform a Standard Annulus Pressure Test (SAPT) on the well. At the time of the inspection, there were no areas of concern. EPA enforcement staff will continue to use information gathered during the inspection to determine compliance with EPA UIC regulations.