



REGION 4

ATLANTA, GA 30303

SENT VIA ELECTRONIC MAIL

Anthony Scott
Owner
201 S 78th St.
Tampa, Florida 33619
ascott@big3dieselrepair.com

Dear Anthony Scott:

On March 20, 2024, the Environmental Protection Agency Region 4 Air Enforcement Branch conducted an inspection of JAKS Automotive Enterprise LLC dba Big 3 Diesel & Automotive Repair facility located in Tampa, Florida. We have enclosed the final inspection report generated for this inspection (Enclosure A).

The EPA previously sent Big 3 Diesel & Automotive Repair a copy of the draft inspection report in an email dated May 6, 2024, allowing Big 3 Diesel & Automotive Repair the opportunity to make any comments on the report and to claim any information contained in the report as confidential business information (CBI). In an email on May 15, 2024, Big 3 Diesel & Automotive Repair notified the EPA that the company does not wish to claim any part of the inspection report as CBI.

If you have any questions regarding this inspection report, please contact me at 404-562-9727, or by email at rivera.lorianny@epa.gov.

Sincerely,

LORIANNY RIVERA

Digitally signed by LORIANNY
RIVERA
Date: 2024.05.17 09:08:15 -04'00'

Lorianny Rivera
Environmental Scientist
South Air Enforcement Section

ENCLOSURE A
INSPECTION REPORT

Clean Air Act Title II: Mobile Source Inspection

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	March 20, 2024
EPA Region/Program Conducting Inspection:	EPA Region 4 Air Enforcement Branch
Company Name:	JAKS Automotive Enterprise LLC dba Big 3 Diesel & Automotive Repair
Facility Name:	Big 3 Diesel & Automotive Repair
Facility Physical Location: (street address, building/unit #)	201 S 78 th St.
(City, state, zip code)	Tampa, Florida 33619

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Lorianny Rivera

Field Inspector Name

LORIANNY RIVERA

Digitally signed by LORIANNY RIVERA
Date: 2024.05.17 09:08:56 -04'00'

Signature

Date

Todd Groendyke

Name of Approving
Official

Chief, SAES

Title

TODD GROENDYKE

Digitally signed by TODD
GROENDYKE
Date: 2024.05.16 15:25:33 -04'00'

Signature

Date

Clean Air Act Title II: Mobile Source Inspection

FACILITY INSPECTION WORKSHEET

General Inspection Information			
Facility Name:	Big 3 Diesel Repair	Inspection Date	3/20/2024
Facility Address:	201 S 78 th St. Tampa, Florida 33619	Arrival/Departure Time	9:45 AM EDT 11:32 AM EDT
		Inspection Number/ID:	3601643854
Primary Facility Representative & Title:	Anthony Scott, Owner	Inspector(s):	Lorianny Rivera Aleeka Broner
Facility Contact Phone/Email:	607-316-9186 ascott@big3dieselrepair.com		
Time Inspector Presented Credentials:	10:02 AM EDT	Compliance Assistance Materials Provided to Facility:	U.S. EPA Small Business Resources Information Sheet Enforcement Alert
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No		
	Anthony Scott		
Photographer Name:	N/A	Photograph Range:	N/A
Additional Personnel Present:	N/A	Areas Discussed:	☒ CBI ☒ Equipment (OBD scanner, camera) ☒ Safety Requirements
Facility Summary:	The business opened in 2013, but they have been in the current location since 2019. The company works on repairs for light and medium-duty trucks. The repairs consist of oil changes, oil leaks, engine work, and suspension. Approximately 95% of the workload pertains to diesel vehicles, with the remaining 5% allocated to gas vehicles. The company has five employees: three technicians and two in the office.		

Facility Business Activities			
Types of Services (Check all that apply)		Description/Observations (Types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☐	Sells aftermarket parts		
☒	Service shop	The parts ordered are mostly OEM, typically from Ford, Dodge, AutoZone, and Advance Auto Parts. In the shop, 18-20 trucks were being serviced.	The company services approximately 40 vehicles per month.
☐	Fleet		
☐	Other:		

Personnel Interviewed			
Name	Title/Position	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Anthony Scott	Owner	ascott@big3dieselrepair.com 607-316-9186	Rivera

Documents Requested			
Document(s)	Status		Notes/Comments
Reviewed some service invoices for June, November, and December of 2023.	☒ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
Service orders for September, October, and November 2023.	☐ Document(s) Provided ☒ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	Please send via email rivera.lorianny@epa.gov
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	