

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	09/23/2024	Time	12:30
		Operator Representative	Performance Energy Resources, LLC		
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS4530000		
		API Well No			
		Lease Name	JACKSON		
		Well ID	12		
Location	SE 03 24N 11E	Status	Inactive	Well Type	Disposal
Latitude	36.582553	Longitude	-96.107735		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Performance Energy Resources		
Inspect No.		Date Last MIT	01/23/2018	Last Test Result	Fail
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 542
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Speedy Well Service (SWS) run in well OS4530000 to 2050 feet below land surface and spot 10 sacks of class A cement. SWS pulled up hole and shut down until 9/24/2024 to allow bottom plug to harden.				
Inspector Signature					
Supervisor Signature					