

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 2 3											
						Year-Month-Day: 2 0 2 4 – 0 4 – 3 0											
						EPA Permit # (or RA):											
						Page 1 Of 2											
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 2:47 pm																	
End Time: 2:49 pm																	
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC																
	Street Address: 5415 Oil Plant Rd																
	City: Jay County: Santa Rosa State: FL Zip: 32565																
	Nature of Business: oil and gas production																
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702																
	Email:																
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319																
	O/O Mailing Address: 5415 Oil Plant Rd																
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565																
	Well Name & #: ALICE BRAY #20-3 API No. 0911320080 PA No. 311594																
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_591																
	Latitude (°N): 30.943977 Longitude (°W): -87.183548 Elevation (ft):																
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing																
	PBBDT: 15944' ☐ Other: surface casing 9 5/8" at 3807'																
	Total Depth (ft): 16036' Inner Casing Size (in): 7" at 16009' Tubing Size (in): 3 1/2" at 15480' Packer Depth (ft): 15480'																
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15675' Bottom(ft): 15775' Max. Injection Pressure (psig): 7500 N2 gas 4400psi PW																
Field Measurements and Observations	Latitude (°N): 30.944015 Longitude (°W): -87.183488 Elevation (ft):																
	EPA GPS ID: S75332 Well Status (see table): AC If not Active, Reported Date Last Active:																
	Nature of Injected Fluid(s) if any: Produced Waters (PW)																
	General Condition of the Well Site:																
	Notes & Comments (include discrepancies from database values):																
	DANGER sign is posted: H2S May Be Present..Authorized Personnel Only..Hazardous Operations...																
	An identification sign was posted on site for the Tubing gauge: 400 psi																
	injection well. Production gauge: 0 psi																
	This well is actively injecting produced fluids. Surface gauge: 0 psi																
	Flow line gauge:																
See reverse for additional observations, comments and photo log																	
UIC Inspector								UIC Inspector									
Name: Carol Chen								Name:									
Signature: CAROL CHEN								Signature:									
Digitally signed by CAROL CHEN Date: 2024.06.20 21:27:57 -04'00'																	
Version 2018-04-18																	

[illegible][illegible]

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID: RIMG0151 Time: 2:47 pm Lat (°N): 30.944018 Long (°W): -87.183457

Description: injection well, well identification sign and DANGER sign posted: H₂S May Be Present...Hazardous...

Photo ID: RIMG0152 Time: 2:48 pm Lat (°N): 30.944015 Long (°W): -87.183488

Description: surface gauge reads 0 psi

Photo ID: RIMG0153 Time: 2:48 pm Lat (°N): 30.944017 Long (°W): -87.1834

Description: tubing injection gauge reads 400 psi

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____