

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/03/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Atlas Operating, LLC	
Facility Name:	Battery 7	
Facility Physical Location:	32.047973, -95.474527	
(city, state, zip code)	Quitman, Texas 75783	
Mailing address:	1900 St. James Place, Suite 800	
(city, state, zip code)	Houston, Texas 77056	
County/Parish:	Wood County	
Facility Phone Number	281-893-9400	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011253	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Atlas Operating, LLC oil and gas facility located near Quitman, Texas on 03/03/2020 for an unannounced inspection. There were no representatives of Atlas Operating, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as Battery 7 and has a state identification number of: RRC #036587.

Section II - OBSERVATIONS

I observed recent work on the berm around the tank battery during the inspection. I saw some oil staining in a small creek nearby to the facility but did not observed produced water in the creek.

Section III – AREAS OF CONCERN

There was recent surface damage observed outside of the tank battery.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A