

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/25/2024	Time	10:30
		Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS0812000		
		API Well No			
		Lease Name	Blackburn		
		Well ID	2		
Location	NE 04 22N 07E	Status	Inactive	Well Type	Disposal
Latitude	36.414166	Longitude	-96.554521		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT		Last Test Result	
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 719
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Calgary Energy, LLC run in hole to 2400 feet and tag the top of the bottom cement plug, then mud the hole from 2400 feet to 450 feet. Operator then perforated the casing at 450 feet, 350 feet and 250 feet. Operator then ran in to 450 feet below the surface and circulated 84 sacks of cement to the surface. Inspector observed cement standing at the surface in the casing with no fall back.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.414166, -96.554521		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010498

Orientation: N/A

Date of Photo: 7/18/2024

Time of Photo: 7:23 PM

Latitude: 36.414166

Longitude: -96.554521

Photographer: Matthew Allen

Description: This was well OS0812000 with cement standing full in the casing with no fall back.