

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	12/21/2022	Time	11:15
Inspection Due	2021-04-03T00:00:00Z	Operator Representative	Grace Energy Management, Inc.		
Operator Info	Grace Energy Management, Inc. P.O. Box 515 Cement, OK 73017 Phone: 405-489-7126	Inventory ID	OK0088000		
		API Well No			
		Lease Name	SECPSU (Kla-Da-Ing 1)		
		Well ID	1-1		
Location	NW 10 05N 09W	Status	Active	Well Type	Enhanced Recovery
Latitude	34.924817	Longitude	-98.1399		
Inspection Reason	MIT	Responsible Company at Time of Inspection	Grace Energy Management		
Inspect No.		Date Last MIT	01/31/2017	Last Test Result	Acceptable
Casing	5.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 641
FLM Canister Pressure		Actual Pressure	0		Max Volume 300
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OK0088000. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Initial: 220psi Mid: 220psi Final: 220psi Pressure Hold OK Total flowback: 7,500ml				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 34.924817, -98.1399		
City: Verden	County/Parish: Grady	State: Oklahoma



Photo File Name: R0010012

Orientation: N

Date of Photo: 12/21/2022

Time of Photo: 11:33 AM

Latitude: 34.924817

Longitude: -98.1399

Photographer: Matthew Allen

Description: OK0088000 well sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 34.924817, -98.1399		
City: Verden	County/Parish: Grady	State: Oklahoma



Photo File Name: R0010013

Orientation: N

Date of Photo: 12/21/2022

Time of Photo: 11:34 AM

Latitude: 34.924817

Longitude: -98.1399

Photographer: Matthew Allen

Description: Well, OK0088000 with EPA gauge and bleeder assembly attached, well pressured and being observed during MIT.