

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/03/2026	Time	
		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS2952000		
		API Well No			
		Lease Name	NRU		
		Well ID	NWN E13		
Location	NE 05 24N 07E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.58759	Longitude	-96.574308		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	06/17/2010	Last Test Result	Acceptable
Casing	5.56	Tubing		USDW	430
Monitoring Device Elected	N	Tubings	Annulus	AUTHORIZED	
Monitoring Device		Fittings	N	N	Max Pressure 725
FLM Canister Pressure		Actual Pressure	0		Max Volume
Lease Status	Active	Determined?	Open Value		Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level	464		
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed well, OS2952000. The well was casing reduced to a 2" ball valve. The fluid level was observed to be 464 feet below the surface. The well was overdue for MIT at the time of the inspection. Great Horned Owls was the new owner of the well but the change of ownership was not yet completed with EPA.				
Inspector Signature					
Supervisor Signature					