

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#: <table border="1"><tr><td>N</td><td>O</td><td>N</td><td>E</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>2</td><td>0</td><td>2</td><td>3</td><td>-</td><td>0</td><td>7</td><td>-</td><td>1</td><td>8</td></tr></table>										N	O	N	E							2	0	2	3	-	0	7	-	1	8
N	O	N	E																															
2	0	2	3		-	0	7	-	1	8																								
Year-Month-Day: <table border="1"><tr><td>N</td><td>O</td><td>N</td><td>E</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>										N	O	N	E																					
N	O	N	E																															
EPA Permit # (or RA): <table border="1"><tr><td>N</td><td>O</td><td>N</td><td>E</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></table>										N	O	N	E																					
N	O	N	E																															
				Page		1		Of		2																								
Inspector(s): <u>Carl E. Weller</u> (lead), <u>Carol Chen</u> Start Time: <u>11:23 am</u>																																		
End Time: <u>11:25 am</u>																																		
Facility Contact Information	Facility Name: <u>Logsdon Valley Oil Co., Inc.</u>																																	
	Street Address: <u>105 Bedford Court</u>																																	
	City: <u>Horse Cave</u> County: _____ State: <u>KY</u> Zip: <u>42749</u>																																	
	Nature of Business: <u>Oil and gas extraction</u>																																	
	Facility Owner/Operator: <u>Logsdon Valley Oil Co., Inc.</u> Phone: <u>270-537-4288</u>																																	
	Email: <u>estinson@scrtc.com</u> <u>Spencer Walters scw106@gmail.com</u>																																	
	Facility Contact (if different): <u>Ellen Stinson, President</u> Phone: <u>270-537-4288</u>																																	
	O/O Mailing Address: <u>105 Bedford Court</u>																																	
Well Data from File	City: <u>Horse Cave</u> County: <u>injection well: Barren</u> State: <u>KY</u> Zip: <u>42749</u>																																	
	Well Name & #: <u>Billy Joe Caudel #UIC-1</u>																																	
	Well Type (see table): <u>Produced Water Disposal</u> State Permit: <u>111143</u>																																	
	Latitude (°N): <u>37.15977</u> Longitude (°W): <u>-85.79628</u> Elevation (ft): _____																																	
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing																																	
	PBDT: ☐ Other: _____																																	
	Total Depth (ft): _____ Inner Casing Size (in): _____ Tubing Size (in): _____ Packer Depth (ft): _____																																	
	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) _____ Bottom(ft): _____ Max. Injection Pressure (psig): _____																																	
Field Measurements and Observations	Latitude (°N): <u>37.15979</u> Longitude (°W): <u>-85.79628</u> Elevation (ft): _____																																	
	EPA GPS ID: <u>SX8123</u> Well Status (see table): <u>AB</u> If not Active, Reported Date Last Active: <u>7/30/2019</u>																																	
	Nature of Injected Fluid(s) if any: _____																																	
	General Condition of the Well Site: _____																																	
	Notes & Comments (include discrepancies from database values): _____																																	
	<u>Unconfined pit, blackened dead trees.</u>																																	
	<u>Metallic enclosure is heavily corroded, collapsed.</u> Tubing Gauge: <u>N/A</u>																																	
	<u>Injection well is disconnected from the injection line. Annulus gauge is non-functioning.</u> Production Gauge: <u>N/A</u>																																	
	<u>Tank battery shows evidence of previous spillage from the top where a pipe was connected, as fluids drained.</u> Surface Gauge: <u>N/A</u>																																	
	See reverse for additional observations, comments and photo log																																	
UIC Inspector Name: <u>Carl E. Weller</u> Signature: <u>CARL WELLER (Affiliate)</u> Digitally signed by CARL WELLER (Affiliate) Date: 2023.08.30 11:08:30 -04'00'						UIC Inspector Name: <u>Carol Chen</u> Signature: <u>CAROL CHEN</u> Digitally signed by CAROL CHEN Date: 2023.08.22 11:30:47 -04'00'																												
Version 2018-04-18																																		

Inspection ID	EPA Well ID#:	N	O	N	E					
	Year-Month-Day:	2	0	2	3	-	0	7	-	1 8
	EPA Permit # (or RA):	N	O	N	E					
		Page				2		Of		2

[illegible]

Photographer: Carl E. Weller EPA Camera ID: SX8123

Photo ID: 219 Time: 11:23 am Lat (°N): 37.15979 Long (°W) -85.79628

Description: injection well close-up

Photo ID: 220 Time: 11:24am Lat (°N): 37.15977 Long (°W) -85.79625

Description: view of injection well and produced fluids tank

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector

Name: **Carol Chen**

Signature: **CAROL CHEN**

Digitally signed by CAROL CHEN
Date: 2023.08.22 11:31:14 -04'00'