

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	1/13/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Mark Clemishire Oil Company, LLC	
Facility Name:	Russell-Drummond	
Facility Physical Location:	36.312593, -96.400907 (N/2 Sect. 12, T 21N, R 8E)	
(city, state, zip code)	Osage, Oklahoma 74054	
Mailing address:	P.O. Box 661	
(city, state, zip code)	Hominy, Oklahoma 74035	
County/Parish:	Osage County	
Facility Phone Number	918-637-9938	
Facility Contact:	Mark Clemishire	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		28 FEB 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Mark Clemishire Oil Company, LLC oil and gas facility located near Oilton, Oklahoma on 01/13/2020 for an unannounced inspection. There were no representatives of Mark Clemishire Oil Company, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Russell-Drummond tank battery.

Section II - OBSERVATIONS

I observed a dry secondary containment area. There was a cut in the berm wall during the inspection and the berms were eroded and inadequate.

Section III – AREAS OF CONCERN

The berms of the secondary containment were inadequate.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA R6 SPCC program.

Section V – LIST OF APPENDICES

N/A