

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 5 8 Year-Month-Day: 2 0 2 4 - 0 4 - 3 0 EPA Permit # (or RA): F L I 0 0 0 9 Page 1 of 2									
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 3:20 pm End Time: 3:22 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating, LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
Well Data from File	O/O Mailing Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Well Name & #: St. Regis SWDS #9-6 API No. 09-113-20206 PA No. 311643														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_1091														
	Latitude (°N): 30.959457 Longitude (°W): -87.192072 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 6800' ☐ Other: surface casing 9 5/8" at 2315'														
Field Measurements and Observations	Total Depth (ft): 6900' Inner Casing Size (in): 7" at 6848' Tubing Size (in): 4 1/2" at 6100' Packer Depth (ft): 6100'														
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 6380' Bottom(ft): 6798' Max. Injection Pressure (psig): 1731 psi														
	Latitude (°N): 30.959438 Longitude (°W): -87.192013 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): TA If not Active, Reported Date Last Active: 2/14/2012														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	sign: Hazardous Operation...Keep Out														
	This is an inactive well. Tubing gauge: 0 psi														
	There is a large pool of fluids just behind the well. Production gauge: 0 psi														
Surface gauge: 0 psi															
Flow line gauge:															
See reverse for additional observations, comments and photo log															
UIC Inspector Name: Carol Chen Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.06.20 21:40:45 -04'00'						UIC Inspector Name: Signature:									
Version 2018-04-18															

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	5	8
	Year-Month-Day:	2	0	2	4	-	0	4	-	3	0
	EPA Permit # (or RA):	F	L	I	0	0	0	0	9		
					Page	2	Of	2			

[illegible]

Photographer: Carla Foy EPA Camera ID: S75332

Photo ID: RIMG0161 Time: 3:20 pm Lat (°N): 30.95933 Long (°W): -87.192032

Description: injection well, identification sign, pool of fluids, sign of Hazardous Operation...Keep Out

Photo ID: RIMG0162 Time: 3:21 pm Lat (°N): 30.959438 Long (°W): -87.192013

Description: production and surface gauges

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector
Name: _____
Signature: _____