


Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 10:23 AM

Project: Ice Cube, Fall River, MA



Location: 41.7521944392327, -71.0953138833314

Photos:



Description:


Photo ID: 1

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 10:24 AM

Project: Ice Cube, Fall River, MA



Location: 41.751924412727, -71.0938869197429

Photos:



Description: Removing stockpile now


Photo ID: 2

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 10:25 AM

Project: Ice Cube, Fall River, MA



Location: 41.7517899571331, -71.0932694569581

Photos:



Description: Retention pond


Photo ID: 3

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 10:28 AM

Project: Ice Cube, Fall River, MA



Location: 41.7519498165106, -71.0923964004086

Photos:



Description: Downslope of stockpile they are removing


Photo ID: 4

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 10:30 AM

Project: Ice Cube, Fall River, MA



Location: 41.7521355112111, -71.0923266433442

Photos:



Description: Silt fence


Photo ID: 5

Field Photo Report

Submitted By:

Submitted Time: June 6, 2024 10:31 AM

Project: Ice Cube, Fall River, MA



Location: 41.7522202636101, -71.0924162099489

Photos:



Description: Another silt fence needs attention


Photo ID: 6

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: June 6, 2024 10:32 AM

Project: Ice Cube, Fall River, MA



Location: 41.7524205940233, -71.0925733019329

Photos:



Description: topped fences


Photo ID: 7

Field Photo Report

Submitted By:

Submitted Time: June 6, 2024 10:32 AM

Project: Ice Cube, Fall River, MA



Location: 41.752365970849, -71.0925066114849

Photos:



Description: Sediment


Photo ID: 8

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: June 6, 2024 10:32 AM

Project: Ice Cube, Fall River, MA



Location: 41.7524668308357, -71.0925361389934

Photos:



Description: sediment leaving site


Photo ID: 9

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 10:33 AM

Project: Ice Cube, Fall River, MA



Location: 41.752432312604, -71.0924554827728

Photos:



Description: Sediment


Photo ID: 10

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 10:33 AM

Project: Ice Cube, Fall River, MA



Location: 41.7524241108044, -71.0925639176254

Photos:



Description: Other section with sediment


Photo ID: 11

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: June 6, 2024 10:34 AM

Project: Ice Cube, Fall River, MA



Location: 41.7525886382695, -71.0929204928729

Photos:



Description: Ravines


Photo ID: 12

Field Photo Report

Submitted By:


Submitted Time: June 6, 2024 10:35 AM

Project: Ice Cube, Fall River, MA



Location: 41.7526906767971, -71.0929206195567

Photos:



Description: Silt fence needs attention


Photo ID: 13

Field Photo Report

Submitted By: Stephanie Tougas


Submitted Time: June 6, 2024 10:36 AM

Project: Ice Cube, Fall River, MA



Location: 41.7529830738828, -71.0929342207626

Photos:



Description: Conservation easement sign


Photo ID: 14

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 10:37 AM

Project: Ice Cube, Fall River, MA



Location: 41.7530173920238, -71.0929366885523

Photos:



Description: Need to clean catch basin



Photo ID: 15

Field Photo Report

Submitted By: Eleanor Horvath

Submitted Time: June 6, 2024 10:38 AM

Project: Ice Cube, Fall River, MA



Location: 41.7532197111256, -71.0936359065979

Photos:



Description: Seeded but still breached



Photo ID: 16

Field Photo Report

Submitted By:


Submitted Time: June 6, 2024 10:39 AM

Project: Ice Cube, Fall River, MA



Location: 41.7532202331694, -71.0936389253464

Photos:



Description: Seeded slope



Photo ID: 17

Field Photo Report

Submitted By: Stephanie Tougas

Submitted Time: June 6, 2024 10:41 AM

Project: Ice Cube, Fall River, MA



Location: 41.7532661817631, -71.0937770590355

Photos:



Description: Sediment needs attention

Photo ID: 18