Monsanto LOSS AND DAMAGE INSPECTION REPORT

1-3	D.C.C. 4-5	CLAIM NUMBER (6-13)	SW 14	15
DS1	1			1

LOCATION: ELIZABETH NJ

DATE: 9/16/68

REPORT NUMBER: # 15

SHIPPER	ORIGIN	(16-19)	DATE RECEIVED (20-25)
MONSANTO CO	ANNISTON ALA		9/16/68

CONSIGNEE (26-45)	DESTINATION CITY (46-55)	STATE (56-59)	DATE UNLOADED
MONSANTO CO	ELIZABETH	NJ	9/16/68

MONSANTO SHIPPER'S NUMBER	MONSANTO ACCOUNT NUMBER	DATE CARRIER INSPECTED
SN 574411		SEAL NUMBERS

DELIVERING CARRIER	CAR OR TRAILER NUMBER (DESIGNATE WHICH)	WAYBILL OR PRO (DESIGNATE WHICH)
MALONE FRT LINE		S 04991

DESCRIPTION OF EXCEPTION (NUMBER, SIZE AND TYPE OF CONTAINERS OF DAMAGED OR LOST MATERIAL AND PRODUCT NAME DAMAGED OR NOT DELIVERED) (FOR DAMAGED EQUIPMENT INDICATE, DAMAGE OF EQUIPMENT AND PACKAGING IN DETAIL INCLUDING DRAWING USING SUPPLEMENTARY PAGES IF NECESSARY TO DESCRIBE DAMAGE AND ALSO HAVING PAGES SIGNED BY CARRIER.)

10 x 60 AROCLOR 1262
20 x 600 AROCLOR 1242
48 x 600 AROCLOR 1254 (3 DRUMS REFUSED - DAMAGED LEAKING)

TYPE OF CLAIM (60)
1 ☐ LOSS
2 ☒ DAMAGE

GENERAL DESCRIPTION OF DAMAGE

TYPE OF TRANSPORTATION (61)
1 ☐ RAIL
2 ☒ TRUCK
9 ☐ PLAN III
5 ☐ OTHER PIGGYBACK
6 ☐ BARGE
8 ☐ AIR
8 ☐ OTHER (SPECIFY)

TYPE OF RAIL EQUIPMENT (62)
1 ☐ CUSHION UNDERFRAME
2 ☐ DAMAGE FREE
3 ☐ DAMAGE FREE W/CUSHION UNDERFRAME

TYPE OF CONTAINER (63-64)
10 ☐ BAG
92 ☐ CAN
30 ☒ METAL DRUM
20 ☐ FIBRE DRUM
91 ☐ WOOD BOX
91 ☐ FIBREBOARD BOX
51 ☐ TANK CAR
53 ☐ BULK HOPPER
90 ☐ OTHER (SPECIFY)

CONDITION OF PACKAGE (65-66)
01 ☐ WET
02 ☐ STAINED
03 ☒ LEAKY
04 ☐ CRUSHED
05 ☐ TORN OPEN
10 ☐ ONLY OUTSIDE PLY TORN
06 ☐ PUNCTURED (thru to product)
11 ☐ PUNCTURED (not thru to product)
☐ SEAMS BROKEN
08 ☐ TAPE LOOSE
09 ☐ OTHER (SPECIFY)

LOCATION OF DAMAGE (WITHIN VEHICLE) (67-68)
01 ☒ AT FRONT END (TRUCK)
02 ☐ AT REAR END (TRUCK)
03 ☐ AT "A" END (RR)
04 ☐ AT "B" END (RR)
05 ☐ ALONG SIDEWALLS
06 ☐ ON FLOORS
07 ☐ IN DOORWAY AREA
08 ☐ ON TOP OF LOAD
09 ☒ WITHIN LOAD
10 ☐ THRU OUT LOAD
11 ☐ OTHER (SPECIFY)

CONDITION OF CARRIER EQUIPMENT (69)
1 ☒ NEW 5 ☐ OLD
2 ☐ DIRTY 6 ☐ CLEAN
3 ☐ NAILS PROTRUDING
4 ☐ OTHER (SPECIFY)

PROTECTION PROVIDED (70)
01 ☐ ON SIDES
02 ☐ ON ENDS
03 ☐ ON FLOORS
04 ☐ AT DOORWAYS
05 ☐ WITHIN LOAD
06 ☐ OTHER (SPECIFY)

CONDITION OF LOAD (71-74)
1 ☐ LOAD SHIFTED (indicate number of inches)
2 ☐ NO INDICATION OF LOAD SHIFT
4 ☐ LOAD PALLETIZED
5 ☐ PALLETIZED WITH GLUING OR TYING
6 ☒ EVIDENCE OF LEAKING
7 ☐ NO EVIDENCE OF LEAKING
8 ☐ LOAD DISARRAYED

ADDITIONAL INFORMATION (ONLY IF ABOVE DOES NOT DESCRIBE DAMAGE SUFFICIENTLY)

DRUMS CRACKED ON BOTTOMS

CARD #2

(FOR COMPLETION BY ST. LOUIS CLAIM DEPARTMENT)

	CLAIM AMOUNT (16-22)	% (23-25)	DIV. (26-27)	PRODUCT CODE MAJOR GRADE (28-34)	T/R 35	DELIVERING CARRIER (36-45)	CARRIER CODE (46-49)	CLAIM WEIGHT (50-55)
15								
2								

DAMAGE INSPECTED BY CARRIER
☐ BEFORE UNLOADING
☒ DURING UNLOADING
☐ AFTER UNLOADING
☐ WAIVED BY CARRIER

IS MATERIAL SALVAGABLE
☒ YES
☐ NO
☐ UNABLE TO DETERMINE

DISPOSITION OF MATERIAL
☒ REJECTED TO CARRIER
☐ ACCEPTED
☐ HELD FOR LOCAL MONSANTO INSTRUCTIONS

CARRIER INSPECTOR (Signature): Earl Crump

MONSANTO REPRESENTATIVE (Signature): [signature]

DISTRIBUTION OF COPIES
Copy 1 TO MONSANTO HOME OFFICE FOR CLAIM AGAINST CARRIER (WHITE)
Copy 2 TO CARRIER (YELLOW)
Copy 3 TO ORIGINATING MONSANTO PLANT (PINK)
Copy 4 RETAINED BY RECEIVING LOCATION (GOLD)

TF-65 REV. 8-65

MONSANTO COMPANY
800 North Lindbergh Boulevard Saint Louis, Missouri 63166

PCB-ARCH-EXT0378105