

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	06/15/2023
EPA Region/Program Conducting Inspection:	U.S. EPA, Region 4 Air Enforcement Branch
Company Name:	Pensacola Fuel Injection Inc.
Facility Name:	Pensacola Fuel Injection Inc.
Facility Physical Location: (street address, building/unit #)	4703 N Palafox Street
(city, state, zip code)	Pensacola, FL 32505

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Aleeka Broner

Field Inspector Name

ALEEKA BRONER

Signature

Digitally signed by ALEEKA
BRONER
Date: 2023.07.27 12:31:32 -04'00'

Date

Todd Groendyke

Name of Approving
Official

Section Chief, SAES

Title

Groendyke, Todd

Signature

Digitally signed by Groendyke,
Todd
Date: 2023.07.27 13:17:05 -04'00'

Date

FACILITY INSPECTION WORKSHEET

General Inspection Information			
Facility Name:	Pensacola Fuel Injection Inc.	Inspection Date	6/15/2023
Facility Address:	4703 N Palafox Street Pensacola, FL, 32505	Arrival/Departure Time	1:45 EDT 3:20 EDT
		Inspection Number/ID:	3601535675-2023
Primary Facility Representative & Title:	Atonia Walters, Secretary	Inspector(s):	Aleeka Broner, Tony Spann
Facility Contact Phone/Email:	850-470-9408 pensacolafuel1@aol.com		
Time Inspector Presented Credentials:	1:50 EDT	Compliance Assistance Materials Provided to Facility:	Small Business Resources Information Sheet, OECA Enforcement Alert, Exhaust System Repair Guidelines
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No		
	Atonia Walters, Secretary		
Photographer Name:	N/A	Photograph Range:	N/A
Additional Personnel Present:	N/A	Areas Discussed:	☒ CBI ☒ Equipment (OBD scanner, camera) ☐ Safety Requirements
Facility Summary:	Pensacola Fuel Injection Inc. headquartered in Pensacola, FL, is a retailer that offers aftermarket performance parts to customers worldwide. The company offers parts for sale online through their website and eBay.		

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☒	Sells aftermarket parts	The facility indicated that they offer aftermarket parts for diesel vehicles and agricultural machinery.	Estimated 250 sales/month
☐	Service shop		
☐	Fleet		

Clean Air Act Title II: Mobile Source Inspection

☐	Other:		
--------------------------	--------	--	--

Personnel Interviewed			
Name	Title/Position	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Atonia Walters	Secretary/Bookkeeper/Treasurer	850-470-9408 pensacolafuel1@aol.com	Broner

Documents Requested		
Document(s)	Status	Notes/Comments
Sales records for May 2023	☒ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	Inspectors reviewed hardcopy records onsite.
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	

Vehicles Inspected/Observed				
VIN (last 4 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Data Obtained? (Yes/No)	Observations (e.g., Who Performed Apparent Tampering?)
N/A				