

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/16/2022	Time	09:15
Inspection Due	2019-11-13T00:00:00Z	Operator Representative	Wilson, Clay S		
Operator Info	Wilson, Clay S Po Box 1212 Pawhuska, OK 74056 Phone: 918-645-6866	Inventory ID	OS1936000		
		API Well No			
		Lease Name	Whitetail		
		Well ID	6		
Location	NW 30 27N 10E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.789619	Longitude	-96.273751		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Clay S. Wilson		
Inspect No.		Date Last MIT	08/19/2014	Last Test Result	Acceptable
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings	Annulus	AUTHORIZED	
Monitoring Device		Fittings	Y	Y	Max Pressure 560
FLM Canister Pressure		Actual Pressure	-14	0	Max Volume
Lease Status		Determined?	UIC Staff Gage	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?	Echo Meter		
Flowline Hooked Up?	Y	Injection Rate (bpd)	0		
Injecting	N				
Inspection Comments	Well OS1936 (Whitetail No. 6) was connected to the flowline at the time of the inspection and the 2 inch ball valve on the tubing and flowline were both closed, preventing injection. At the time of the inspection there was 14 in.Hg vacuum on the tubing and 0 psi pressure on the annulus of the well. I observed the fluid level down the tubing of the well using an Echometer, the fluid level was 1088.70 feet below the top of the tubing. The well sign should be updated. There were no areas of concern at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.789619, -96.273751		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0672

Orientation: N

Date of Photo: 8/16/2022

Time of Photo: 9:17 AM

Latitude: 36.789619

Longitude: -96.273751

Photographer: Jeanne Eckhart

Description: This was well OS1936000 (Whitetail No. 6) with the EPA Echometer attached, just prior to obtaining a fluid level measurement.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.789619, -96.273751		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0674

Orientation:

Date of Photo: 8/16/2022

Time of Photo: 9:31 AM

Latitude: 36.789619

Longitude: -96.273751

Photographer: Jeanne Eckhart

Description: This was the EPA gauge displaying 13 in.Hg of vacuum on the tubing of well OS1936000.