

CELANESE CHEMICAL COMPANY
Chemcel Plant
Bishop, Texas

PLAINTIFF'S
EXHIBIT

CEL-285

TO: Mr. G. E. Wallace

FROM: W. H. Brough

WHB-340

April 8, 1980

Landfill Material at Pond 13E,
Pond 13E Alternate and New Asbestos Landfill Site.

On Wednesday, March 19, the following articles were landfilled in there designated sites;

1. Pond 13E:

50 crushed drums were landfilled in the Plant South East corner of Pond 13E.

2. Pond 13E Alternate:

50 crushed drums were landfilled in the landfill site know as 13E Alternate. The location of the landfill was Plant North of the Plant North entrance road to Pond 13E.

3. New Asbestos Landfill Site:

Several bags of asbestos containing insulation were buried in the Plant North East corner of the new asbestos landfill area located on the existing Plant Landfill Site 3.

Enclosed is a plot plan indicating the landfill sites that I have designated above. Also enclosed is work order 4-9167 with the instructions for burial of the above mentioned items.

If there are any questions regarding this designation and disposal, please contact me.

UNITERMS
LANDFILL
ASBESTOS
MATERIAL

W. H. Brough
W. H. Brough

lk

Encl.

101544

000247

BM-R CPL VR El. In. A.I.n. Lb. Ma. S.M.a. PF W O.C. ABI															WORK ORDER 4-9167								
6	Cost Ctr.	8	9	Lbr. Class	11	12	Mtl. Class	14	15	Material Estimate				23	24	Labor Estimate				32			
2	2	7	5	1	7	3	1																
33	Equipment Name																		64				
33	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2	2				
65	Writer	67	68	Catg.	Number				73	Date				79	80	Approval Operations				Approval Maintenance			
2	J	J																					
WORK REQUESTED: 100 CRUSHED DRUMS & BAGS OF INSULATION																		Priority					
INSTRUCTIONS: IMPROVED WITH REMOVED INSTRUCTIONS																		Safety Permit		Yes No			
																		Shutdown Required					
																		Date Available					
JUSTIFICATION: Instructions																							
Comp. In. J. J.																							
Complete by: L. L.										Date				Apprv. Mgr.									

DATE - 3/19/80


AVO -

- ①. Bury 50 crushed, RT drums Plant North of Pond 13 E. in Pond 13 E Alternate landfill site
- ②. Bury 50 crushed, RT drums in Plant South east corner of Pond 13 E landfill site.
- ③. Bury bags of insulation in Plant Northwest corner of new asbestos disposal area.

W. Branga

000248

000010



LA
F.II

000250

000051




F

E

LAND
FILL HERE

← 50
crushed
drums



NEW ASBESTOS
LANDFILL
EXISTING
ASBESTOS SITE

ASBESTOS
LANDFILL

000251

000050

S.W. III

S.W. III

[illegible]

7A

7B

=

3

4

8A

8B

5
IP
I
IV
E1
A1 A2

II

8D

8C

III

U.S. PLASTICS COMP.

000253

000054

IV.

REFERENCE DRAWINGS

C

CHINESE
CHEMICAL CO., INC.

4
PRODUCTION AREA

CHINESE
S COMPANY

000255

000255

3

2

CELANESE CHEMICAL COMPANY, INC
A DIVISION OF CELANESE CORPORATION OF AMERICA
CHEMCEL PLANT - BISHOP, TEXAS
ENGINEERING DEPARTMENT

CELANESE CHEMICAL CO., INC
CHEMCEL PLAN
PITS, PONDS, AND LAGOONS

S.M. NO.	W.O. NO.
ACCT NO.	EST. NO.
DRAWN BY <i>Qm S</i>	DATE 10-13-78
CHECKED BY	DATE
REQ. ENGR.	DATE
SR. LDR.	DATE
PLANT ENGINEER	DATE

AREA	UNIT	SCALE	DRAWING NO.
TYPE OF DRAWING		NONE	

B

A

000256

000057