

Out-Remove from Stores
Stock

TABLE

ASBESTOS RELATED PROBLEMS, COMMENTS, AND SUGGESTED SOLUTIONS

ITEM	DESCRIPTION	COMMENTS	SUGGESTED SOLUTIONS
a.	Asphalt Mastic	No problem unless sprayed	Do not spray
b.	Braided Packing	Contained, considered safe to handle	Personnel monitoring to verify claim
c.	Asbestos Gloves	Probable source of exposure	Personnel monitoring. Look for substitute
d.	Heat Suits	Same as f.c.	Look to aluminized "Nomex" as substitute
e.	Hot Pads	Same as f.c.	Same as f.c.
f.	Insulation	Separate listing	See Item 2
g.	Molded packing	Contained, no problem	None required
h.	Sheet gasketing	Contained, no problem	None required
i.	Calcium Silicate	Probable source of high exposure	Personnel monitoring to verify claim. Look for substitute material.
j.	Inhibited Calcium Silicate	Same as 2.a.	Same as 2.a.
k.	Kaylo 20	Same as 2.a.	Same as 2.a.
l.	Asbestos Board	Problem when saved	Same as 2.a.
m.	Asbestos Roofing Felt	Contained, no problem	None required
n.	Fibrated asphalt Emulsion	No problem unless sprayed	Do not spray
o.	Fibrated asphalt Cut-back	Same as 2.f.	Same as 2.f.
p.	Asbestos Cloth (listing tape)	Possible source of high exposure	Personnel monitoring to verify claim. Evaluate J-M Thermo-chem tape as substitute.

DUP 0900982

135

121311

1-B-7A

Asbestos
1992

ASBESTOS RELATED PROBLEMS, COMMENTS AND SUGGESTED SOLUTIONS

ITEM	DESCRIPTION	COMMENTS	SUGGESTED SOLUTIONS
i.	Asbestos cloth (insulation fittings)	Same 2.h.	Same as 2.h.
j.	Fire resistive Fibrated Asphalt Cut-back	Same as 2.f.	Same as 2.f.
k.	Fibrated Asphalt Dispersion	Same as 2.f.	Same as 2.f.
l.	Asbestos paper	Probably safe to handle	Personnel monitoring to verify claim
m.	Flexible Braided Asbestos Tubing	Possible Source of high exposure	Personnel monitoring to verify claim
n.	"Tedlar" Neoprene Asbestos Laminate	Probably safe to handle	Same as 2.l.
	"Hypalon" Neoprene Asbestos Laminate	Same as 2.l.	Same as 2.l.
p.	Fibrous Adhesive	Contained, no problem	None required
.a.	Insulation Storage	Possible source of high exposure	Thorough vacuum cleaning, repeat periodically. Personnel monitoring to verify claim.
.a.	Dismantling	Possible source of high exposure	Soak with water. Personnel monitoring
b.	Installing Calcium Silicate Insulation	Probable source of high exposure	Personnel monitoring. Substitute as quickly as possible.
c.	Waste Disposal	Regulated by OSHA	Follow 37 FR 11321 Part 1910.93a h.2.

DUP 0900983

LB-75
JUL 9 1992

JOSEPH J. HARRIS

121312