



INTER-OFFICE CORRESPONDENCE

To: Mark Wood

Date: October 20, 1976

From: P. J. Snyder

Location: 10 West

Subject: Lake Charles
Air Monitoring

Per your request, please find attached part of the summary I have previously worked up on Lake Charles air monitoring. I hope this information can help answer any question you may have concerning this matter.

The breakdown for vinylidene chloride (VDC) monitoring from April 1975-1976 is as follows:

<u>JOB</u>	<u>NO. SAMPLES</u>	<u>MAX. NO.</u>	<u>NO. > 10 PPM</u>
EDC Operator	16	5.6	--
MC Operator	20	12.5	2
MC Aux. Operator	25	43.0	5
P/T Rx Operator.	21	2.8	--
P/T Still Operator	24	15.6	2
P/T Aux. Operator	16	8.4	--
VC Proc. Operator	15	.38	--
VC Furn. Operator	16	1.0	--
EC Operator	9	1.2	--
P/T Tetra. Operator	6	1.5	--
OCH Operator	10	.60	--
OHC Aux. Operator	10	.32	--
Cell Repair	--	--	--
P/T Lead Operator	3	.33	--
Cell Builder	--	--	--
Welder	--	--	--
Lab Assoc.	12	4.1	--
Lab Assistant	2	1.12	--
Lan Analyst	4	.10	--
Lab Sr. Analyst	1	.11	--
Loader	9	2.8	--
Loader Helper	8	10.0	1
Pipefitter	2	96.0	1
Hg Circ. Operator	--	--	--
Hg Area Foreman	--	--	--
Maint. Helper	2	1.7	--
Machinist	--	--	--
Shippers	--	--	--
Shippers	--	--	--
Packer	--	--	--
Brine Trtmnt. Operator	--	--	--

TOTAL 231 Samples of VDCM

P. J. Snyder

P. J. Snyder

/zak
Attachments