



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, ILLINOIS 60604**

DATE: OCT 25 2018

SUBJECT: CLEAN AIR ACT INSPECTION REPORT
Buckeye Terminals, LLC - Cuyahoga, Cuyahoga Heights, Ohio

FROM: Luke Hullinger, Environmental Engineer
AECAB (MI/WI)

THRU: Sarah Marshall, Section Chief
AECAB (MI/WI)

TO: File

BASIC INFORMATION

Facility Name: Buckeye Terminals, LLC - Cuyahoga

Facility Location: 4800 E 49th Street, Cuyahoga Heights, Ohio

Date of Inspection: 8/28/2018

EPA Inspector(s):

1. Luke Hullinger, Environmental Engineer
2. Kenneth Ruffatto, Environmental Engineer

Other Attendees

1. Steve Reichard, Terminal Operator A, Buckeye Terminals
2. Kim Trostel, Sr. Air Quality Specialist, Buckeye Terminals

Contact Email Address: ktrostel@buckeye.com

Purpose of Inspection: Tanks inspection

Facility Type: Bulk Storage Terminal

Regulations Central to Inspection: 40 C.F.R. Part 63 Subpart BBBBBB

Arrival Time: 9:00 AM

Departure Time: 10:30 AM

Inspection Type:

- ☒ Unannounced Inspection
☐ Announced Inspection

OPENING CONFERENCE

- ☒ Credentials Presented
☒ CBI warning to facility provided

The following information was obtained verbally from Steve Reichard or Kim Trostel unless otherwise noted.

Process Description:

Buckeye Terminals, LLC - Cuyahoga is a bulk storage terminal located on the Cuyahoga River in Cuyahoga Heights, Ohio. They receive petroleum liquids by truck and store them onsite until they are sent off by either truck. The facility has a vapor recovery unit that turns on during loading and routes displaces emissions from the truck to the subgrade tank. The Bulk storage tanks all have a capacity of over 500,000 gallons and have floating roof tanks.

TOUR INFORMATION

EPA toured the facility: Yes

Data Collected and Observations:

EPA used a FLIR Camera to observe a leaking vent on top of Tank 1.

Photos and/or Videos: were taken during the inspection.

Appendix A

RECORDS REVIEW

1. List of tanks, and capacities (copy received)

CLOSING CONFERENCE

Concerns: EPA noted Tank 1 was leaking off a vent on top of the tank.

SIGNATURES

Report Author: Luke Hall Date: 10/22/2018

Section Chief: [Signature] Date: 10/25/18

Facility Name: Buckeye Terminals, LLC - Cuyahoga
Facility Location: 4800 E 49th Street, Cuyahoga Heights, Ohio
Date of Inspection: 8/28/2018

APPENDICES AND ATTACHMENTS

I. Appendix A – Video log

Facility Name: Buckeye Terminals, LLC - Cuyahoga
Facility Location: 4800 E 49th Street, Cuyahoga Heights, Ohio
Date of Inspection: 8/28/2018

APPENDIX A: DIGITAL IMAGE LOG

1. Inspector Name: Luke Hullinger	2. Date(s) of Inspection: 8/28/2018
3. Company/Facility Name: Buckeye Terminals, LLC - Cuyahoga	4. Street Address, City, State: 4800 E 49th Street, Cuyahoga Heights, Ohio
5. Number of Images: 1	6. Archival Record Location: C:\Users\Lhulling\OneDrive - Environmental Protection Agency (EPA)\Buckeye Terminals - Cuyahoga

Image Number	File Name	Description of Image
1	MOV_2002.mp4	Leaking vent on Tank 1

