

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
11-17-01 1330	5394 CN	GC 3 2	8.4	P. Williams	no	no	found nothing			
11-17-01 1420	5395 CN	GC 3 2	5.5	Rx 741 Rinse H ₂ O line between Rinse H ₂ O supply valve & reactor P. Williams	yes 100-300 ppm	yes 174632	Patched line with FAB-A NEW LINE AND REPLACE 11-27-01	11/17/01	D. Carington	D. Carington
11-18-01 0610	5396 CN	GC 5 2	10.0	Tank Farm	no	no	Trapped VC in lines, pulled lines down again			
11-18-01 0609	5397 CN	GC 4 #3	7.2 10 5.1	Tank Farm	no	no	same as above			
11-18-01 0700	5398 CN	#1 #1	10.5 7.9/6.3	Tank Farm	no	no	No vacuum at Tank Farm cut line, tank pulled hydro down and shut off			
11-18-01 0735	5399 CN	GC 5 7	10.0 6.3	P. Williams	no	no	found nothing			

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.