

**CHLORINATED METHANES PLANT
RX. CHEM INCIDENTS
SINCE 1992 CONSOLIDATED AUDIT REVIEW**

1. METHYL CHLORIDE CAUSTIC FILTERS (5/92)

- OPERATOR EXPOSURE TO NAOH/WATER PLUME
- WELL COMMUNICATED
- A MAIN DRIVING FORCE FOR PROCEDURE SYSTEM

2. ALUMINUM BAFFLED TANK TRUCK/M1 (9/94)

- NEW TRANSPORTATION SERVICE
- POOR KNOWLEDGE OF RXN POTENTIAL & MATERIALS OF CONSTRUCTION
- DETAILED PROCEDURES FOR DISPOSAL DEVELOPED

DO A 032566
CONFIDENTIAL