

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/02/2024	Time	09:50
		Operator Representative	Performance Energy Resources, LLC		
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS4629000		
		API Well No			
		Lease Name	HUDSON		
		Well ID	3		
Location	SW 20 27N 12E	Status	Inactive	Well Type	Disposal
Latitude	36.797145	Longitude	-96.043127		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Performance Energy Resources		
Inspect No.		Date Last MIT	05/14/2004	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings	Annulus	AUTHORIZED	
Monitoring Device		Fittings	N	N	Max Pressure 399
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed surface restoration was completed at the well location.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.797145, -96.043127		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010517

Orientation: WNW

Date of Photo: 9/23/2024

Time of Photo: 9:54 AM

Latitude: 36.797145

Longitude: -96.043217

Photographer: Matthew Allen

Description: : This was the well location for well OS4629000 after surface restoration had been completed.