CALIFO. IA INSPECTION RATING B .EAU

WORKMEN'S COMMITTEE MINUTES

PLAINTIFF'S EXHIBIT KM-327

COMPANY KELLY-MOORE PAINT CO., INC. DATE OF MEETING 3/27/72
ADDRESS 1015 Commercial St., San Carlos, Calif.

MEMBERS PRESENT

Name	Position	Name	Position	Name	Position
Lee Jacobs	Filler, Paco				
Carl Hanson	Order Picker K-M				
Vincent Palomar	Janitor K-M				
James Ferguson	Tinter K-M				

A PLANT TOUR WAS MADE BY THE COMMITTEE AND THE FOLLOWING NEW RECOMMENDATIONS WERE MADE (Describe and number consecutively)

1. PAINT PLANT:
    1. Rags not covered in mixing area.
    2. Thinner drums not covered, near Sandmill.
    3. Grounds not connected, Tinting area.

2. LACQUER PLANT:
    1. Rags by filling stand in corner.

3. P V A ROOM:
    1. Junk under high tank.
    2. Pallets around corner in back.

4. TRUCK SHOP:
    1. Could stand good cleanup. Rags & other material in improper place.

5. YARD:
    1. Full of pot holes.

KMX 00286

6. WOOD WORKING SHOP:
    1. No safety glasses on while working with machines.
    2. Wood not in proper order.

7. METAL SHOP:
    1. No gloves worn while working with metal.

MEETING OPENED 9:20 ADJOURNED 10:30 DATE & TIME OF NEXT MEETING continued 4/24/72 9:20

File 1 copy for CIRB INSPECTOR
Attach 2 copies to General Committee Minutes
for transmittal to Liberty Mutual Loss Prevention
LPSX 61

Signed James P. Ferguson
CHAIRMAN (Sign all copies)

Printed in USA