



Applied Environmental Services

"Consultants in Wastes Management and Environmental Control"

ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO

SUITE 320

EL PASO, TEXAS 79902

(915) 533-4108

PLAINTIFF'S EXHIBIT

CHV-797

22 December 1987


Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Sample No.	Time-m	Flow-l	Fibers/cc
S-46, c-pipeway, area removal	420	3600	<0.01
S-47, c-pipeway, pers removal	420	840	<0.01
S-48, c-pipeway, area removal	420	3600	<0.01
S-49, c-pipeway, pers removal	420	840	<0.01

Sincerely,


Howard G. Applegate
Ph.D.



Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL

PROJECT: CHEVRON

DATE: DECEMBER 21, 1987

ANALYZED BY: DR. HOWARD APPELEGATE

DATE: DECEMBER 22, 1987

SAMPLE NO.	S-46	S-47	S-48	S-49				
SAMPLE LOCATION	C-PIPE WAY REMOVAL AREA SAMPLE	C-PIPE WAY REMOVAL PERSONAL SAMPLE	C-PIPE WAY REMOVAL AREA SAMPLE	C-PIPE WAY REMOVAL PERSONAL SAMPLE				
FILTER SIZE (mm)	25	25	25	25				
START TIME	9:15 am	9:17 am	9:19 am	9:21 am				
END TIME	4:15 pm	4:17 pm	4:19 pm	4:21 pm				
RATE OF FLOW (lpm)	15	2	15	2				
TOTAL TIME (hrs)	7	7	7	7				
VOLUME SAMPLED (l)	6300	840	6300	840				
RESULTS (f/cc)	< 0.01	< 0.01	< 0.01	< 0.01				