

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's (EPA's) inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	December 14, 2022
EPA Region/Program Conducting Inspection:	EPA Region 4/Mobile Source Program
Company Name:	ACME Logistics
Facility Name:	ACME Logistics
Facility Physical Location: (street address, building/unit #)	327 West Phillips Road
(city, state, zip code)	Greer, South Carolina 29650

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Carrie Griffith

Field Inspector Name

CARRIE GRIFFITH Digitally signed by CARRIE GRIFFITH
Date: 2023.02.13 09:10:21 -05'00'

Signature

Date

Todd GroendykeName of Approving
OfficialChief, SAES

Title

TODD GROENDYKE Digitally signed by TODD
GROENDYKE
Date: 2023.01.25 12:32:53 -05'00'

Signature

Date

FACILITY INSPECTION WORKSHEET

(Supplemental notes or narrative format may be used as preferred).

General Inspection Information			
Facility Name:	ACME Logistics	Inspection Date	12/14/2022
Facility Address:	327 West Phillips Road Greer, SC 29650	Arrival/Departure Time	11:14 EST 13:09 EST
		Inspection Number/ID:	0400000045045EPA27-2022
Primary Facility Representative & Title:	Reed Erskine, President	Inspector(s):	Carrie Griffith Lorianny Rivera
Facility Contact Phone/Email:	854-801-4000 ext 215 rerskine@acmelogistics.net		
Time Inspector Presented Credentials:	11:20 EST	Compliance Assistance Reference Materials Provided to Facility	☐ SBREFA Form ☐ Exhaust Repair Guidelines ☐ Memo 1A ☐ Tampering Brochure ☐ Engine Switch Fact Sheet ☐ Other:
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No		
	Reed Erskine		
Photographer Name:	Lorianny Rivera	Photograph Range:	1343-1365
Notes (e.g. compliance actions taken by facility, purchased samples, other relevant background, etc.):	ACME Logistics is the “corporate center” of several affiliated but separate freight transportation-related entities in South Carolina. This facility specializes in the transportation of healthcare, pharmaceutical, and general freight.		

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts (hardware or software)		
☐	Sells aftermarket part sales (including drop shipments)		
☐	Service shop		
☒	Fleet	This terminal operates 10 vehicles on a schedule of 5 years in service per vehicle.	Annual revenue \$2-3M.
☐	Other:		

Personnel Interviewed			
Name	Title/Position	Contact Info	Interviewed by
Reed Erskine	President	864-801-4000 ext 215 rerskine@acmelogistics.net	Griffith

Documents Requested		
Document(s)	Status	Notes/Comments
Maintenance records for all vehicles in fleet.	☒ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	Inspectors spot checked maintenance files and reviewed records for vehicles 349, 352, 354, 359, and 356 onsite.
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Document(s) Denied ☐ Will Provide After Inspection ☐ Other (see notes)	

Vehicles Inspected/Observed				
VIN (last 4 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Data Obtained? (Yes/No)	Observations (e.g., Who Performed Apparent Tampering?)
1278	NCEXH0408BCA	No	Yes	No signs of tampering observed.
2636	Engine label not observed	No	Yes	No signs of tampering observed.