

Leak Detection and Elimination Sheet

ABD00147909

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
4-19-01 0645	4186 CN	GC5 1	5.6	CE		NO	ON VALVE ON BOOM LEFT CRACKED closed off		ce	
4-19-01 0655	4187 CN	GC5 8	10.0	nothing found PW Penetration	NO	NO				
4-22-01 06:00	4188 TB	GC #1 #2 #4 #3	8.5 5.8 5.8	VCN EAST UNLOAD CHPR SHED - PRESSURE IN LENS POTS	—	NO	VALUED OFF EMS SYSTEM NEW VCM UNLOAD SPOT - VALVE CRACKED OPEN	4/22/01	R6	R6
4-20-01 2213 2224	4189 AS	#1	10.0 6.6	VCN RAILROAD UNLOADING COMPRESS. SHED	LO	YES 133703 133704 133705	tighten patch on #1 #4 #5			
4-21-01 03:04	4190 AS	#6	8.2	VCN STORAGE SPHERE	NONE	NO	NOTHING FOUND DC			
4-22-01 16:00	4191 TB	#1 #1	5.1	4th Compd	4.5 YES	NO	flat line looking elaborate 4 Compd	7/22/01	RS	RS

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.