



Applied Environmental Services
"Consultants in Wastes Management and Environmental Control"

ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO

SUITE 320

EL PASO, TEXAS 79902

(915) 533-4108

PLAINTIFF'S EXHIBIT

CHV-800

02 December 1987

Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Number	Time-minutes	Flow-lpm	Fibers/cc
/ S-32, area I, area	6600	15	0.01
/ S-33, area I, pers	880	2	<0.01

Sincerely,

Howard G. Applegate
Ph.D.



Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: Darla Environmental

PROJECT: Chevron

DATE: 12-01-87

Chevron BB
015594

ANALYZED BY: Howard G. Applegate

DATE: 12-02 87

SAMPLE NO.	S-34	S-35	S-36	S-37				
SAMPLE LOCATION	PERSONAL AIR SAMPLE WHITE DUMPING ASBESTOS	PERSONAL AIR SAMPLE WHITE DUMPING ASBESTOS	PERSONAL AIR SAMPLE REMOVAL	AREA AIR SAMPLE REMOVAL				
FILTER SIZE (mm)	25	25	25	25				
START TIME	9:00	9:02	11:30	11:32				
END TIME	11:00	11:02	3:30	3:32				
RATE OF FLOW (lpm)	2	2	2	15				
TOTAL TIME (hrs)	2	2	4	4				
VOLUME SAMPLED (l)	240	240	480	3600				
RESULTS (f/cc)	< 0.01	< 0.01	< 0.01	< 0.01				